

SURVEY &
REMONUMENTATION

1933

LIBER

1 PAGE 439

REMONUMENTATION
COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac
(County)

Located In:

Corner Code #

- | | | |
|---------------------------------------|---------------------------|-----------------------|
| 1. Public Land Survey | T <u>11N</u> R <u>15E</u> | D - 13, <u>C - 13</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 4. Lot No. _____, Recorded Plat _____ | | |
| 5. Private Claims _____ | | |

RECEIVED FOR RECORD

93 DEC 29 AM 11:03

LIBER NO. 439
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

I, John A Milletics, in a field survey on Oct 15, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

D - 13

Found 1/2" iron bar in gravel road bed, per survey dated 2-13-1980

C - 13

Found Monu Box in centerline of paved surface, per survey dated 2-13-1980

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D - 13

S 1/4 Cor Section 32 T11N-R15E
Found 1/2" iron bar

C - 13

SW Cor Section 32 T11N-R15E
Found Monu Box

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D - 13

S 1/4 Cor Section 32 T11N-R15E
1/2" iron bar
N55°E 107.14' to a nail in a Power Pole
N60°W 41.25' to a nail in a Mail Box Post
N55°W 105.20' to a nail in a Power Pole
West 2653.45' to the SW Cor Section 32

C - 13

SW Cor Section 32 T11N-R15E
Monu Box
N45°E 60.20' to a nail in a Power Pole
N50°W 80.20' to a nail in a Power Pole
S10°E 61.15' to a nail in a Power Pole

Signed by

John A Milletics

Date

Dec 24, 1993

Surveyor's Michigan License No.

25859