

1993

LIBER 1 PAGE 438

REMONUMENTATION COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac (County) Located In: Corner Code #
1. Public Land Survey T 11N R 15E F - 13, E - 13
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

RECEIVED FOR RECORD

93 DEC 29 AM 11:03

LIBER 1 PAGE NO. 438
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

I, John A. Milletics, in a field survey on Oct 13, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Grid table with columns A-M and rows 2-13. Numbers 1-36 are placed in the grid cells.

A. Description of original monument and accessories and/or subsequent restoration:

F - 13

Found 1/2" iron bar in gravel road bed, per survey recorded in Liber 3 Page 420 of the Sanilac County Records

E - 13

Found 1/2" iron bar in gravel road bed, cap NO 16041

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F - 13

S 1/4 Section 33 T11N-R15E
Found 1/2" iron bar

E - 13

SW Cor Section 33 T11N-R15E
Found 1/2" iron bar

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F - 13

S 1/4 Cor Section 33 T11N-R15E
1/2" iron bar
N45°E 59.00' to a nail in a Power Pole
N55°E 70.80' to a nail in a Power Pole
S45°W 43.15' to a nail in a 20" Maple
S20°E 31.30' to a nail in a 6" Ash

E - 13

SW Cor Section 33 T11N-R15E
1/2" iron bar
S05°W 34.40' to a nail in a 6" Poplar
S10°E 38.70' to a nail in a 6" Poplar
N70°E 75.60' to a nail in a 8" Poplar
N20°E 27.65' to the East end of a 12" CMP

Signed by John A. Milletics

Date Dec. 24, 1993

Surveyor's Michigan License No. 25859