

SURVEY &  
REMONUMENTATION

1993  
REMONUMENTATION  
COMMISSION

LIBER 1 PAGE 434

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Sanilac</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>11N</u> R <u>15E</u>	<u>L - 13</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

RECEIVED FOR RECORD

93 DEC 29 AM 10:56

LIBER 1 PAGE NO. 434  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

I, John A. Millerics, in a field survey on Oct 13, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

L - 13

Found Monu Box in paved surface, per State Highway Right of Way Book

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L - 13

S 1/4 Cor Section 36 T11N-R15E

Found Monu Box

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L - 13

S 1/4 Cor Section 36 T11N-R15E

Monu Box

N50°W 77.15' to a Nail in a Fence Post

East 14.00 to the Centerline of pavement

N60°E 53.45' to a Stop Sign

S50°W 56.95' to a Right of Way Marker

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Signed by

*John A. Millerics*

Date Dec 24, 1993

Surveyor's Michigan License No. \_\_\_\_\_

25859