<sub>ag</sub> amés,	the contract of the contract o	
REWORL	diameter to the same	

JAN 1 9 2000

SECTION

LIBER 2 PAGE 340

1999 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

99 NOV 30 AM 9: 03

LIBER HO PAGE NO 34
MICHELE VANNORMAN
REGISTER OF DEEDS
SANIL & C.C., HICHIGAN

For corners in

SANILAC	Located In:	Corner Code #			
(County)					
1. Public Land Survey	T <u>12 N</u> R T R T R	14 E A-10			
2. Property Controlling in Section	TR S TR S TR				
Miscellaneous     Property in Sec.	S TR S TR				

Register of Deeds Stamp & File Number

t. Lot No	, Recorded Plat
D. 1	
5. Private Claims	

I, John A. Milletics, in a field survey on Aug. 2, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	, <u>A</u>	B		D	Ε	F	G	H	Ι	J	K	L	М
			1						Ţ	Ī			
2	2 ├	6-	┿	~ 5 –	+	- 4 -		— <del>3</del> —	+	- <u>2</u> -		– į -	-
:	3	1	4		┸	$\perp$			_	_ _			
		7~	$\perp$	- 8	$\perp$	- 9-	_	-10-	$\downarrow$	-11-	- -	 1 <sub> </sub> 2-	
	5	┸	4	_ _	4	١.			$\perp$	<u> </u>	_ _	_	_
•	5 <u> </u>	 1 <mark>8-</mark>	- -	 -17–	-	-16-	1	 -1,5	ļ	-14	$\downarrow$	 -1 <sub>,</sub> 3-	
-	<b>,</b>	1	$\perp$		4_	_	-	-	╀	_		_ _	
8	₽	19	1	-20		-2 <b>1</b> _	$\perp$	-2 <sub>.</sub> 2	-	-23 <u>-</u>	$\downarrow$	-24-	_
9	,	$\perp$	1	$\perp$	$\perp$	<u> </u>			$\perp$				
1	ф <u> —</u>	 30–	_	-29 <u>-</u>	_	 -28	_	 -27—	1	-26		_25_	-
1	1	+		+	╀		+	+	+-		+	+	$\dashv$
1	2	31—	+-	-32—	-	-3 3		-34-	_	35-		-35-	4
,	2	1	f			1				1			ĺ

A. Description of original monument and accessories and/or subsequent restoration:

A-10 B. Ash 9 N10W 4 1/2; DO 10 S56W 14 1/2 Old Survey Liber - None

L.C.R.C. - Liber 1 Page 328

Act 132 - None

Unrecorded survey - Milletics Dated Sept 1990

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-10

W 1/4 Corner Section 30, T12N-R14E Found 5/8" Iron Bar in Gravel Road Bed North 2649.74 feet to the NW Corner South 2653.20 feet to the SW Corner Accepted as best evidence

APPROVED PEER BOARD MEETING NOV 19,1999

C.	Description of	f monument i	for corner and	laccessories	s established to	perpetuate	locating the	position of	the corner:
----	----------------	--------------	----------------	--------------	------------------	------------	--------------	-------------	-------------

A - 10

W 1/4 Corner Section 30 T12N-R14E

5/8" Iron Bar in gravel Road Bed

North 2649.74 feet to the NW Corner

South 2653.20 feet to the SW Corner

East 38.95 feet to a nail in a 36" Ash

N75°E 45.55 feet to a nail in a 8" Ash

 $N05^{\circ}E$  490.93 feet to the SW Corner of a Bell Riser Box