

JAN 19 2000

LIBER

2 PAGE 343

RECEIVED FOR RECORD

SECTION

1999 REMONUMENTATION PROGRAM  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

99 NOV 30 AM 9:03

For corners in

LIBER NO. 2 PAGE NO. 343  
MICHELE VAHNORMAN  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

SANILAC (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>12</u> N <u>R</u> 14E	A-13
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, John A. Milletics, in a field survey on Aug. 2, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														
2	6			5			4			3			2	1
3														
4	7			8			9			10			11	12
5														
6	18			17			16			15			14	13
7														
8	19			20			21			22			23	24
9														
10	30			29			28			27			26	25
11														
12	31			32			33			34			35	36
13														

A. Description of original monument and accessories and/or subsequent restoration:

A-13 Hemlock 9 West 1 1/4; DO 12 North 24 1/2  
Old Survey Liber - None  
Act 132 - Liber 2 Page 177, Liber 3 Page 160, Liber 3 Page 161  
L.C.R.C. - None  
Unrecorded survey - Kay Eng Dated Jan 1975, Milletics Dated Jan 1991 & Nov 1994

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-13  
SW Corner Section 31, T12N-R14E  
Found Monu Box with 1/2" Iron in place  
North 2652.07 feet to the W 1/4 Corner  
Accepted as best evidence

APPROVED PEER BOARD MEETING  
NOV 19, 1999

*gm*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 13  
SW Corner Section 31 T12N-R14E  
Monu Box with 1/2" Iron bar with cap  
North 2652.07 feet to the W 1/4 Corner  
North 10.5 feet to the centerline of M-46  
N30°E 95.60 feet to a nail in a Power Pole  
S45°E 47.75 feet to a nail in a Power Pole  
S60°W 101.70 feet to a nail in a Tele Pole

Signed by *J.A. Milletics*  
Surveyor's Michigan License No. 25859

Date 11-15-1999