APR 1 4 1998

1. Public Land Survey

Property in Sec.

LIBER

2 PAGE 177

RECEIVED FOR RECORD

## 97 DEC -2 AM 9: 10

## LAND CORNER RECO Filing Requirement of

RDATION CERTIFICATE Act 74, Mich. P.A. 1970	LIBER NO. 2 PAGE NO. 17
	ESTHER LEE REGISTER OF DEEDS SANILAC CO., MICHIGAN

For corners in CUSTER TOWNSHIP Sanilac Located In: Corner Code # (County)

T12N R14E

**SURVEY &** REMONUMENTATION

2. Property Controlling in Section 3. Miscellaneous

JAN 0 8 1998

Register of Deeds Stamp Wile Number

4. Lot No,	Recorded Plat	
5. Private Claims _		

John A Milletics, in a field survey on July 22, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

		В	C D	3	F	G I	ŀ	1	J	<b>( )</b>	. 1
	1				$\top$	T					П
	2	6—	† 5 I	•	— <b>4</b>	<del> </del> :	3 —	<del> -</del> -	2	<del> -</del>	<u> 1</u> —
	3	╁	$\vdash$			<del> </del>	├		<u> </u>	<u> </u>	
	4	<del>-</del>	╀┋		_  -	<del>  1</del>	0-	<u> </u>	ı—	<u> </u> 1	2
	5 —	├		+	-	-		_			_
	6	ļ <mark>e—</mark>	i¦		-16	<del> </del> 1	5	1	4—	_i	3
	7	ऻ	-	-	_						<u> </u>
	8  1	ļ 9—.	2(	$\perp$	_2 <b>1</b>	<del> </del> 2	2-	2	3—	2	4
	نــا و	_		$\perp$		-	<u> </u>			_	
1	10-3	0	-29	+	-28	2	7—	<u></u> 2	6—	2	5
***	11	$\vdash$		+	-	-					
1	.2 -3	1-	3¦2	<b>:-</b>  -	_3 3	<del> </del> _3	4	3	5—	—з	6
	-	[									

A. Description of original monument and accessories and/or subsequent restoration:

E - 2GLO Notes

> Set 1/4 Section Post Hemlock 10 N72°E 26 6 N84°W 9

Old Survey Liber, survey dated Oct 1910 by Nicol

Act 74 None

Act 132 Liber 4 Page 282

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Monu Box with 5/8" Iron Bar

APPROVED PEER BOARD MEETING NOV. 26, 1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E 1/4 Corner Section 5 T12N-R14E Custer Twp. Moun Box in place with 5/8 Iron Bar West 50.58 feet to a nail in a Fence Post N80°E 35.60 feet to top center of a culvert N85°E 44.50 feet to a telephone underground cable sign S20°E 49.15 feet to a nail in a mailbox post South 2639.92 feet to the SE Corner Section 5 North 2910.40 feet to the NE Corner Section 5

No. No.

Signed by \_

Date Nov 12, 1997

Surveyor's Michigan License No.\_ 25859