- Million. Do proposestie et et be-

2 PAGE 354 LIBER

SECTION

RECEIVED	FOR	RECO	RΓ
----------	-----	------	----

1999 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

99 MOV 30 AM 9. O.

For corners in			7
SANILAC	Located In:	Corner Code #	LIBER NO Q PAGE NO 354 MICHELE VANNORMAN REGISTER OF DEEDS SAHILAC CO., MICHEGAN
(County)		·	REGISTER OF DEEDS
1. Public Land Survey	T <u>12N</u> R TR	16 E A-11	SAMERE CO., MICHIGAN
	TR TR	<u></u>	
2. Property Controlling in Section	S TR S T R		
3. Miscellaneous Property in Sec.	S T R S T R	<u> </u>	
r topolity in Goo.	· ·		Register of Deeds Stamp & File Number

, Recorded Plat 4. Lot No. 5. Private Claims

I, John A. Milletics, in a field survey on Aug. 2, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	<u> </u>	В	C I)]	<u> </u>	F (5 F	I	I ·	J F	< I	, M
1	Г	Т		Γ]		
2	├	6	+-	<u> </u>	-	4—	;	3		Ż		
3		 	╄					ļ		-	 	
4	\vdash		\vdash	! 8— !	-	9 1	—1	! .0— !	1	 1 -	1	l .2 l
5		-	·	 -					-			<u> </u>
6	<u> </u>	! 1 <mark>.8</mark>	- 1]]	1	 5 !	1	l 5	1	4	_1	3—
7	<u> </u>	-	<u> </u>	<u> </u>				ļ		ļ	_	_
8		ا 19	<u> </u> 2	<u> </u>	2	1	2	 2	2	! 23	2	4
9		<u> </u>				<u> </u>		<u> </u>				
10		 30—	١.	9	,	 :8—	,	_	_		2	
10		30 <u>—</u>	-					1	2		2)
11)	T	 -					-				
12	:	31	 3	2	3	3—	— 3	4—	— 3	5—	—3	6—
13	L	<u></u>	<u>L</u>	L		L		<u> </u>	L			

A. Description of original monument and accessories and/or subsequent restoration:

A-11 Sugar 24 S40W 48; Sugar 17 N49W 331/2 Old Survey Liber - None

Act 132 - Liber 2 Page 601 L.C.R.C. - None

Unrecorded survey - Sanilac Land Dated July 1979, Milletics Dated Aug 1990 Milletics Dated Feb 1997

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11

SW Corner Section 30, T12N-R16E

Found 1" Iron Bar 6'± West of centerline in gravel road bed

North 2652.72 feet to the W 1/4 Corner

South 2637.10 feet to the W 1/4 Corner

Accepted as best evidence

APPROVED PEER BOARD MEETING NOV 19,1499

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

A - 11

SW Corner Section 30 T12N-R16E

l" Iron Bar in gravel Road Bed 6'± West of centerline

North 2652.72 feet to the W 1/4 Corner

South 2637.10 feet to the W 1/4 Corner

S45°E 52.85 feet to a nail in a Power Pole

N50°E 40.00 feet to a stop sign

550°W 31.52 feet to a stop sign

${\tt N60^\circ W}$ 56.00 feet to a nail in a 9" Ash			and the second
Signed by Charles	Date	11-15-1999	
Surveyor's Michigan License No. 25859			