JAN 2 2 2001

2000 Remonumentation Program

RECEIVED FOR RECORD

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

00 NOV 27 AM 8: 56

For	corners	in
-----	---------	----

Sanilac	Located in:	Corner Code #
(County)		
1. Public Land Survey	T ^{12N} R_ TR_	16E H - 7
2. Property Controlling in Section 3. Miscellaneous	T_R S_ T_R S_ T_R S_ T_R	
Property In Sec.	S IR_	

LIBER HO. 3 PAGE HO. 48
MICHELE VANNORMAN
REGISTER OF DEEDS
SANIL AC CO., MICHIGAN

Register of Deeds Stamp & File Number

. Lot No,	Recorded Plat	
Private Claims		

John A Milletics , in a field survey on May 1, 1900 do hereby state that under aquirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in onformance with regulations and rules therefore as required in the current manual of survey instructions of the Inited States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for nat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan card of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, ecovered, found as expressed below:

IOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

. 7	4	В	С	D	Ε	F	G	H	I	3	Κ !	L M
1		T	Т		T	` [_	1	T	1		T	
2	_	- 6-	+	- 5-	+	- 4	+	- 3	+	- 2	\vdash	1-
3		+	+-	+	+	+	+	+	+-	+-	┼	\vdash
4		· † -	╁	- 8-	+	- - 	+	-10-	+	11	-1	2—
5		+	+	+	+	+	+	+	+-	+-	\vdash	\vdash
6	_	19-	╁	-17-	╁	-16-	+	-15-	+	14—	 - 1	i3—
7		4	4-		4-		+		-	+	 	\vdash
8	_	.19.	\bot	-20-	1	-21-	+	_22_	+	.23	-2	4-
9	_	+	+	+	+	+	+	+	+	+	-	\vdash
10		-30-	+	-29-	-	-28-	+	2 7-	+	26	 -2	5—
11	_	1	4	4	1	\perp	4	\perp	+	┼-	ـ	-
		 -31		32		_33_		_34_		.35—	L,	36
12		-31-	1	1	1	-در- ا				1		Ĭ
13	_	ᆂ	┵_									ب

. Description of original monument and accessories and/or subsequent restoration:

31.0 Notes

Beech 10" N35°E 22 Links Beech 10" S58½°E 12 Links

\ct 132 - Liber 3 Page 240

...C.R.C. Forms - None Inrecorded Surveys - Milletics Aug 1988, Milletics Aug 1990

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1 - 7

; 1/4 Corner Section 15 T12N-R16E

'ound 1/2" Iron Bar in Gravel Road Bed

lest 2638.74 feet to the SW Corner Section 15

ccepted as best evidence



. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Į	_	7
	1	14

Corner Section 15 T12N-R15E

/2" Iron Bar in gravel road bed

North 3't to centerline gravel, North 29.75 feet to the SW Cor of a Riser Box

145°W 56.30 feet to a nail in a 12" Beech

APPROVED PEER BOARD

110°E 31.29 feet to a nail in a 12" Ash

MEETING NOV 25 2000

310°W 25.20 feet to a nail in a 12' Beech Vest 2638.74 feet to the SW Cor. Sec. 15

an

	00 11-101
	John AMlleto
gned by _	Sommi alleto

Date	Nov	16,	2000	

/	
irvevor's Michigan License Ni	o. 25859