	•
REMONUMENTA	TION

98 DEC - | AN 9: 09 LAND CORNER RECORDATION CERTIFICATE

<b>P</b>	Filing Requ	irement of Act 74, N	Mich. P.A. 1970	- BER NO.	2 PA	AGE NO	del	
For corners in					ELE VAI			
Sanilac	Located in: Co	orner Code #	REGISTER OF DEEDS					
(County)				SANI	LAC CO.,	MICHIC	BAN	
1. Public Land Survey	T <u>I3N</u> R <u>15E</u> TR TR TR	<u>A-2</u>						
Property Controlling in Section     Miscellaneous Property in Sec.	STR STR STR STR			Danista	a af Dando	Ciamo 8	Cita Biromb	
			<u> </u>	Registe	o Deeds	Stamp 6	File Numb	
4. Lot No, Reco	orded Plat		1	A B C	DEF	<u> </u>	IJK	
				6	54	<del></del>		
•			3					
, John A. Milletics	_, in a field survey on <u>Oct</u>	12, 19 98 do hereby s	state that under 4		- 8	10-		
conformance with regulations as	gan P.A. of 1970, the corner points r nd rules therefore as required in the cu	urrent manual of survey ins	structions of the	; <del>                                    </del>				
United States Department of the	e Interior, Bureau of Land Managemen ed in lines 3, 4 and 5 above were in co	nt or by a decree of a Court informance with the rules (	of the Michigan	1 1 1	_1716	15-	1,4	
Board of Land Surveyors or I	by a Decree of a Court of Law; es	tablished, re-established,	, monumented,	1 1 1				
recovered, found as expressed l	Delow:		. 8	1 1 1	2021		23	
	rners, all in the same town and ran	ige, may be recorded	9		29-28		26	
on this certificate.	_	1 1			76			
			1 1:		3233	34	35	
			1:	1 1 1				
A. Description of original m	nonument and accessories and/o	r subsequent restoratio	on:					
Old Survey Liber L.C.R.C None Act 132 - Liber Unrecorded Surve Road Comm - None	: 4 Page 260 ey dated 5-30-91 Showi	ing NW & W 1/4	Cor Section	6	િં≩ Land	MIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	tics *	
B. Description of corner ev	vidence found and/or method ap	plied in restoring or ree	stablishing corner:	S. C. C.		Sensos P <sup>ecs</sup>		
					777,1811	ial Sy	A. C. L.	
	the NW Cor Section 6				PEER B	OARD M	1EETING	
South 2640.36 to	o the SW Cor Section $\epsilon$	)	<u> </u>	OV 30,	1998	-9	m	
·	nt for corner and accessories esta	ablished to perpetuate I	locating the positio	n of the c	orner:			
A-2 W 1/4 Corner Se 1/2" Iron Bar w	ction 6 T13N-R15E ith cap		SURVEY &					
West 32.00 to N75°W 56.00 to	a nail in a 24"Maple		REMONUMENTATION  JAN 1 5 1999					
N35°W 87.00 to	a nail in a 24" Maple			· # 7 1 1 1 1	13	JJ		
South 2640.36 f North 2925.68 f	eet to the SW Cor Sec eet to the NW Cor Sec	tion 6 tion 6		SI	ECTION	, descrip		
Signed by	1-Milleto		DateNov	19, 98	3			
Surveyor's Michigan License	e No. 25859							