REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

98 DEC - 1 AM 9: 09

| | Filin | g Requirement of Act 74, Mic | | R NO. 🕹 | PA | GE N | 0.0 | عا |
|---|--|--|--|--|---|------------|-------|--------------|
| For corners in | | | | MICHELE VANNORMAN | | | | |
| Sanilac (County) | Located In: | Corner Code # | | REGISTER OF DEEDS SANILAC CO., MICHIGAN | | | | |
| 1. Public Land Survey | T <u>13N</u> R <u>]</u> TR | | | | | | | |
| Property Controlling in Section Miscellaneous Property in Sec. | TR_ STR_ STR_ STR_ STR | | Regist | er of Deeds | Stamp | & File | • Num | ber |
| 4. Lot No, Rec | orded Plat | | | | | _ | | |
| 5. Private Claims | | | - 1 A B C | DEF | G H | 1 | JK | L |
| | | | 2 6- | 5-1-4 | - - š | + | 2 | - i - |
| requirements of P.A. 74, Michiconformance with regulations a United States Department of the that the corner points mentione Board of Land Surveyors or I | igan P.A. of 1970, the corne nd rules therefore as require le Interior, Bureau of Land M ed in lines 3, 4 and 5 above by a Decree of a Court o | Oct 12, 19 98 do hereby state points mentioned in lines 1 and 2 abid in the current manual of survey instructionagement or by a decree of a Court of were in conformance with the rules of the Law, established, re-established, m | cove were in citions of the 5 he Michigan onumented, 7 | 8 9 | 10 | | 11 | -12- 13- |
| recovered, found as expressed | | | 8 19 | 2021 | 22 | 1-2 | 23 | 24 |
| NOTE: Not more than 2 co on this certificate. | orners, all in the same town | n and range, may be recorded | 9 10 30- | 29 28 | 27 | |)6 | |
| on the columnate. | | | 11 12 -31 | 32-33 | 34 | | 55 | |
| A. Description of original rr | nonument and accessori | es and/or subsequent restoration: | 13 | | | | 1L | |
| -4 GLO Notes - Hem Old Survey Liber L.C.R.C None Act 132 - None | lock 16 S29W 54; r - None e e eys Dated 3-31-8 | • | blishing corner: | ohn A. Mil | chilling in the second | 10 ××× | | |
| Description of corner ex | vidence found and/or me | ethod applied in restoring or reestal | hlishing corner | No. 258 | 59 | | • | |
| A-4 W 1/4 Cor Found 1" Iron Accepted as be North 2651.80 | Section 7 T13N- Bar in Gravel Rest evidence feet to the NW | R15E | | Ssional Silling | 50/19/19/19/19/19/19/19/19/19/19/19/19/19/ | | | |
| | | | | D PEER BO | OARD : | MEET | ING | |
| | | | NOV 30, | 1998 | | <i>9</i> n | | |
| A-4 | nt for corner and accesson | ories established to perpetuate loca | - ' | SURVE | | | | |
| East 50.50 to a | nail in a 10" A | | REM | ONUME | NTAT | ION | İ | |
| N75°E 71.35 to a | a nail in a Powe | r Pole | | 4 - | | | | |

North 2651.80 feet to the NW Corner Section 7 South 2686.68 feet to the SW Corner Section 7 Nov 19, 98 Signed by Date Surveyor's Michigan License No.

S45°W 52.65 to a nail in a Wooden Fence Post

S70°W 44.45 to a nail in a Power Pole

JAN 1 5 1999

SECTION