HEMONUMENTATION

MAY 07 1997

LIBER

\$40°E 69.25 feet to a nail in a Power Pole

\$10°E 37.54 feet to a nail in a Fence Post

520°E 59.00 feet to a Metal Fence Post

2 MARE 35

RECEIVED FOR RECORD

COMMISSION

REMONUMENTION

LAND CORNER RECORDATION CERTIFICATE	: 98	5 DEC	10	AM 11: 56

_	Filing Requir	ement of Act 74, Mich. P.A.	1970 LIBER NO 2 PAGE NO 45	
For corners in			ESTHER LEE	
Sanilac	Located In:	Corner Code ##	REGISTER OF DEEDS SANILAG CO., MICHIGAN	
(County)			SANILAC CO., MICHIGAN	
1. Public Land Survey	T 13N R 15E	B-13 -(C-13)		
	T R			
	T R			
• .	T R			
2. Property Controlling	S T R			
in Section	S T R			
3. Miscellaneous	S		Register of Deeds Stamp & File Number	
Property in Sec.	S T R	l		
4. Lot No Re	ecorded Plat			
			A B C D E F G H I J K L	
		-	2 6 5 4 3 2 - 1 -	
			3	
			4 7 1 9 1 9 1 10 1 10 12	
John A Milletics	in a field survey on June	3 1g 96	5	
		of 1970, the corner points mention	ed - l	
		nd rules therefore as required in t	he 18 17 16 15 15 14 13	
		rtment of the Interior, Bureau of La		
		er points mentioned in lines 3, 4 and		
		of Land Surveyors or by a Decree o monumented, recovered, found		
expressed below:	s-established, monumented, re-	·	10 30 29 28 27 26 25	
	orners, all in the same town a	and range may be recorded	11 1 1 1 1 1	
	orners, an in the same town a	ind range, may be recorded	12 31 32 33 34 35 36	
on this certificate.				
A Description of original s	nonument and accessories as	nd/or subsequent restoration:	13	
• -	nonument and accessories at	No Survey in Old	T dham	
B - 13 GLO Notes	Cantina Dant	Act 74 None	Fiber	
	Section Post			
Hemlock 9 N		Act 132 None	. 1-4-1 10 0 01	
Lynn 9 N	/2 W 1/2	Unrecorded Survey	•	
		Notes from 1.E.C.	Survey dated 12-5-75	
C - 13 GLO Notes	•	No Survey in Old	Liber	
80.00 Set Pos	st Corner	Act 74 None		
Sugar 30 N46		Act 132 Liber 3 P	age 366	
Hemock 30 N59	·			
		applied in restoring or reestab	.,4111111	
B - 13	idence round and/or metriod	applied in restoring of reestable	isling corner.	
·-	ction 31 T13N-R15E			
	on bar in gravel road	hed .		
	5/8" iron bar to east		A John A. Milletics	
III FINE WICH	7,0 IION DAI 10 EAST		Land Surveyor	
C - 13			John A. Milletics Land Surveyor No. 25850	
	k 6.0 feet west of pa	vement centerline		
	k o.o reet west of pa Highway Right of Way		Fig. C. S. S.	
as per scare i	righway Kight of Way	DOGE 1486 00	A Consultation of the Cons	
			The state of the s	
			APPROVED PEER BOARD MEETING	
			12-02-96 97	
	•			
·				
Description of monume	nt for comer and accessories	established to perpetuate loca	iting the position of the corner:	
B - 13		C - 13	,	
≤ 1/4 Corner Section	a 31 T13N-R15E	SE Cor Section	31 T13N-R15E	
1/2" iron bar in gra	n gravel Road Bed Monu Box			
	ast 43.70 feet to a 5/" iron Bar S45°E 81.60 feet to a Gas Post			

-igned by July		Date <u>Aug 24, 1996</u>
urveyor's Michigan License No.	25859	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

West 2538.69 feet to the SW Cor of Section 31 West 2643.18 feet to the S 1/4 Cor Section 31

East 6.00 feet to the Centerline of Pavement

N50°E 105.60 feet to a nail in a Power Pole

N45°W 52.50 feet to a nail in a Tele Pole