## REMONUMENTATION

indicate the

98 DEC -1 AH 9: 10

LAND CORNER RECORD Filing Requirement of Ac	DATION CERTIFICATE ct 74, Mich. P.A. 1970LIBER NO. 2 PAGE NO. 276
For corners in  Sanilac Located In: Corner Code #	REGISTER OF ASSET
1. Public Land Survey  T14N R12E	SAIVILAC CO., MICHIGAN
Property in Sec. STR	Register of Deeds Stamp & File Numb
4. Lot No, Recorded Plat	A B C D E F G H I J K  1
NOTE: Not more than 2 corners, all in the same town and range, may be record on this certificate.	rded 9 20 21 22 23 2  10 30 29 28 27 26 2  11 12 31 32 33 34 35 3
A. Description of original monument and accessories and/or subsequent rest  A-13 GLO Notes - Hemlock 12 S59W 11; Beech 10 S79E 20 Old Survey Liber - Survey by F.F. Rogers Old Survey Liber - Survey by Galbraith L.C.R.C - Tuscola Co. Records Act 132 - None	
B. Description of corner evidence found and/or method applied in restoring of A - 13 Found Concrete Monument with 2" Brass Cap Accepted as best evidence East 2135.03 feet to the S 1/4 Corner Section 3	Maria Constitution of the
	APPROVED PEER BOARD MEETING NOV 30, 1998
C. Description of monument for corner and accessories established to perpetu	uate locating the position of the corner:
A-13 Concrete Monument with 2" Brass Cap N35°E 62.80 to a nail in the SE Face of a Pole S42°E 37.09 to a nail in a Telephone Pole S64°W 61.80 to a nail in a Power Pole	SURVEY & REMONUMENTATION  JAN 1 5 1999
N20°W 138.21 to a nail in a Power Pole East 2135.03 feet to the S 1/4 Corner Section 31	
Signed by	DateNov 20, 1998