Remonumentation

2. Property Controlling

in Section 3. Miscellaneous

For corners in

2 PAGE 56 LIBER

## LAND CORNER RECORDATION CERTIFICATE

<b>**</b> : 1 :	D					
ruing	Requirement	ot	ACt 74,	Mich.	P.A.	1970

_	Sanilac	Located In:	Corner Code ##		
	(County)	Loodlog III.			
1.	Public Land Survey	T 14N R 12 E	C - 11 C - 12		
		T R			
		T R			
		T R			

RECEIVED FOR RECORD

95 JUL 10 AM 9: 27

LIBER NO. 2 PAGE NO. 50 ESTHER LEE REGISTER OF DEEDS SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

Property in Sec. \_\_ , Recorded Plat \_ 4. Lot No. \_ 5. Private Claims \_

R.

S \_\_\_\_ R \_

S \_\_\_\_ R \_\_

John A Milletics , in a field survey on \_ May 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-11 GLO Notes

Set Post Beech 22 N67°E 40 - Hemloch 14 N61°W 29 ct 74 Form Liber 1 Page 362 Act 132 Forms Liber 3 Page - Liber 3 Page 293 oad Comm. None Drain Comm None, State Highway Right of Way Book Page 11

Set Post at 40 Chains Cedar 8 S48W 8 - Cedar 6 N13°W 28 \_ct 74 Form None Act 132 Form Liber 3 Page 293 State Highway Right of Way book Page 11 \_oad Comm None, Drain Comm None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Monu Box in Place NE Cor Section 31 T14N-R12E

Approved Peer Group Meetimg May25,1995

C - 12Found P.K Nail E 1/4 Cor Section 31 T14N-R12E

SURVEY & REMONUMENTATION

JUL 3 1 1995

## COMMISSION

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-11 NE Cor Section 31 T14N-R12E C - 12E 1/4 Cor Section 31 T14N-R12E

Monu Box

Monu Box

580°W 51.28 to a nail in a 18"Ash

N45°E 74.28 to a nail in a Power Pole S45°E 69.60 to a nalipin a Power Pole

East 64.48 to a nail in top of Fence Post

S45°W 67.80 a R/R spike in a Power Pole

S70°E 71.14 to a nail in a Power Pole

East 4.3' to the centerline of pavement

1.20 to the centerline of pavement CHILLIAN TO THE PART OF THE PA

John A. Milletics Surveyor Land Surveyor No. 25859

May 22, 1995

∟rveyor's Michigan License No.

25859

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED JAN., 1983