LICER

2 PAGE 283

RECEIVED FOR RECORD

98 DEC -1 AM 9:11

| REMONUMENTA | TION |
|-------------|------|
| | |

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 LIBER NO. PAGE NO. 283

| For corners in Corner Code # | MICHELE VANNORMAN REGISTER OF DEEDS |
|---|---|
| Sanilac (County) ——————————————————————————————————— | SANILAC CO., MICHIGAN |
| 1. Public Land Survey T14N R12E M-13 T R T R T R | |
| 2. Property Controlling in Section S T R | Register of Deeds Stamp & File Number |
| 4. Lot No, Recorded Plat | A B C D E F G H I J K L M |
| | 3 |
| I, John A. Milletics, in a field survey on Nov 1, 1998 do hereby state the requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above conformance with regulations and rules therefore as required in the current manual of survey instruction. United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lav. United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lav. Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monurecovered, found as expressed below: | v and for 6 19 17 16 15 14 13 |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. | $\begin{array}{c ccccccccccccccccccccccccccccccccccc$ |
| | 13 |
| A. Description of original monument and accessories and/or subsequent restoration: M-13 GLO Notes - Birch 10 N70 1/2E 14; Maple 8 West 5 1/2 Old Survey Liber - None L.C.R.C None Act 132 - Liber 2, Page 246 (CASE) | State of Michigan |
| Road Comm - None B. Description of corner evidence found and/or method applied in restoring or reestab | John A. Milletics Land Surveyor No. 25859 No. 25859 |
| M - 13 SE Corner Section 36 TI4N-R12E Found 5/8" Iron Bar raised with 1/2" Iron Bar Found 5/8" Iron Bar raised with 3/2" Iron Bar Found 5/8" Iron Bar raised with 3/2" Iron Bar | Minney Co. |
| as recorded in Liber 2 , Page 246 | APPROVED PEER BOARD MEETING NOV 30, 1998 |
| C. Description of monument for corner and accessories established to perpetuate loc | ating the position of the corner: SURVEY & REMONUMENTATION |
| M - 13 SE Corner Section 36 T14N-R12E 1/2" Iron Bar with cap | JAN 1 5 1999 |
| 1/2" Iron Bar with cap South 32.70 feet to a nail in a Wooden Fence Post S05°E 48.40 feet to a nail in a 12" Poplar S40°W 38.75 feet to a nail in a Wooden Fence Post S65°W 53.50 feet to a nail in a Wooden Fence Post West 2621.60 feet to the S 1/4 Corner Section 36 | SECTION |
| Chill Mille | DateNov 20, 1998 |
| Signed by | |