

Element of the Control of the Contro	OFFICIAL GOVERI	NMENT CORNER	2 U20 - 1	7
MAR 1 6 1999	LAND CORNER RECOI	RDATION CERTIFICAT	TE .	
SECTION	Filing Requirement of	Act 74, Mich. P.A. 1970		
	Located In: (Corner Code #		リロンロ
1. Public Land Survey	T <u>3N</u> R <u>15E</u> TR	A-1		Í
3. Miscellaneous S	T R T R T R T R T R T R T R T R T R T R		Register of Deeds Stamp & File Number	
	Recorded Plat		ABCDEFGHIJKL	
19 98, do hereby certify to 1970, the corner points mowith regulations and rules instructions of the United Management or by a decomentioned in lines 3, 4 and Michigan Board of Land	, in a field survey on October that under requirements of Pentioned in lines 1 and 2 about therefore as required in the confere of a Court of Law and/ord 5 above were in conformated Surveyors or by a Decretal, monumented, re-monumer	A. 74, Michigan P.A. of ve were in conformance current manual of survey interior, Bureau of Land or that the corner points ince with the rules of the see of a Court of Law;	2 6 5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3-3-4-5-8-
NOTE: Not more than 1	CORNER, may be recorded	on this certificate.	13	

ST. CLAIR COUNTY, MICHIGAN

A. Description of original monument and accessories and/or subsequent restoration:

Wood post set as original corner by William Preston, in April 1817. This corner is common to M-1 of T3N-R14E, M-13 of T4N-R14E, and A-13 of T4N-R15E. This corner is also on the county line between St. Clair County and Macomb County. Old County Surveyors record lists corner ties but does not describe monumentation. August 1961, Consumers Power Co. survey set a P.K. nail in pavement listed on survey. George Avendt, in March 1973, recovers and records a 1" iron pin in a monument box, see Liber 2, page 76. Herbert Kobs, in April 1973, recovers and records a 1" iron bar in mounument box, see Liber 2400, page 289 (Macomb Co.). Ken Thompson in a survey dated September 1, 1977 recovered and recorded a P.K. nail in pavement, see Liber 2863, page 957 (Macomb Co.). Steve Dunn in a survey dated December 9, 1993, recovered and recorded a 1/2" iron rerod in monument box and replaced with a Macomb County Remon Cap #28408 on a 3/4" iron rod, in monument box, see Liber 6165, page 980 (Macomb Co.).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 3/4" iron rod with a Macomb County Remonumentation Cap #28408 in a monument box at the approximate center of pavement intersection of Marine City Highway and County Line Road. Verified corner using previously recorded corner witnesses and measuring distances to previously measured quarter corners. Measured north to E 1/4 corner Section 36, M-12 of T3N-R14E, 2715.75' (R), 2715.80' (M). Measured east to N 1/4 corner Section 6, B-1 of T3N-R15E, 2685.34' (R), 2685.36' (M). Measured south to W 1/4 corner Section 6, A-2 of T3N-R15E, 2698.89' (R) 2698.59' (M). This corner approved by Macomb County Remon. Group on December 20, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Did not disturb and used the 3/4" iron rod with the Macomb County Remon. Cap #28408 in the existing monument box at the center of intersection of Marine City Highway and County Line Road. This corner is common to M-1 of T3N-R14E, M-13 of T4N-R14E and A-13 of T4N-R15E.

N 44°W 67.91' to a set P.K. nail with SCC Remon tag in SW face of utility pole.

N 50°E 63.79' to a set P.K. nail with SCC Remon tag in SE face of utility pole.

S 38°E 57.27' to center top of a found concrete Right-of-Way marker.

S 49°W 66.22' to a found P.K. nail in the NW face of a utility pole.

* •		
•	ſ	
C 1	1	
 Date December	4	1998

DEC. 8, 1998

Signed by	D. Duna		200 oyo	Section 1	Date	December	4.1998
Surveyor's Michigan License No.	24608	,		,			
Surveyors Michigan License No	24608.	· · · · · · · · · · · · · · · · · · ·				B00K	009 PAGE 211