

ST. CLAIR COUNTY, MICHIGAN OFFICIAL GOVERNMENT CORNER

MAR 1 5 2000

SECTION

CLERK REGISTER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ST. CLAIR COUNT RECEIVED FOR RECORD Corner Code # Located In: COLUMBUS TOWNSHIP DEC 22 1999 000 5N R 15E B-13 1. Public Land Survey T 2. Property Controlling S Т R in Section Ţ R 3. Miscellaneous S Т R Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims D G H = IK 2 I, MICHAEL J. ROSSOW, in a field survey on AUGUST 10 19_99_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 5 conformance with regulations and rules therefore as required in the current 7 manual of survey instructions of the United States Department of the Interior, 8 Bureau of Land Management or by a decree of a Court of Law and/or that the 9 corner points mentioned in lines 3, 4 and 5 above were in conformance with 10 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of 11

NOTE: Not more than 1 CORNER, may be recorded on this certificate.

Law; established, re-established, monumented, re-monumented, recovered,

A. Description of original monument and accessories and/or subsequent restoration:

B-13, 1817, W. PRESTON OF GLO (MADE SECTION CORNER ON A 6" BLCK ASH TREE)

- (A) 1942, OLD ST. CLAIR COUNTY SURVEYORS RECORD (FINDS & WITNESSES A 1 1/2" PIPE RECORDS NO OFFSET TO NORTH 1/2 CORNER OF SECTION 6)
- (B) 1971, W. SODERBERG LCRC L.1, P.89 (FINDS A 787 ROD INSIDE A MONUMENT BOX & WITNESSES THE SAME)
- (C) 1974, B. COLLINS LCRC L.2, P.200 (FINDS A 1/2" IRON PIPE, NO MENTION OF MONUMENT BOX & WITNESSES THE SAME)

12

- (D) 1930, MDOT RIGHT-OF-WAY MAP (GRAPHICALLY SHOWS ONE COMMON CORNER, B-13 & B-1, FILE #77-R-2)
- (E) 07-07-93, R. KREGER (IDENTIFIES CORNER & RECORDS LOCATION BY ELECTRONIC DATA COLLECTION, NO WITNESSES)
- SEE BACK OF SHEET

found as expressed below:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A ½" REROD INSIDE A STANDARD MONUMENT BOX USING & VERIFYING INFORMATION IN PART "A" ABOVE:

NORTH EAST 61.35' TO NORTH W.F.L. 36" DRIVEWAY CMP TO HOUSE #10304 (S) P.K. IN DETROIT EDISON POLE SOUTH EAST 120.80' (G)(S)
P.K. IN DETROIT EDISON POLE SOUTH WEST 70.95' (G)(F)(H)(J)(L)(N)(R)
67.85' NORTH WEST TO SOUTH EAST BRICK POST OF PORCH (A)(C)(E)(J)(L)
365.8' EAST TO CENTERLINE OF GRATIOT ROAD (120' WIDE) (I)(M)(O)(Q)
NORTH NORTH EAST 31.5' TO P.K. IN POWER POLE (G)(F)(H)(J)(L)(N)(R)
NORTH EAST TO P.K. IN 30" COTTONWOOD (G)(F)(H)
NORTH 107.95' TO SOUTH WEST CORNER OF HOUSE (BRICK) #10304 (S)
THIS CORNER COMMON TO B-1, CASCO TOWNSHIP, T.4N., R.15E.

PA 345-1990 PETT COMMITTEE ATT. JUVED 12:15-99L

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET A 2" DIAMETER ALUMINUM CAP WITH MAGNET ATTACHED & INSCRIBED "ST. CLAIR COUNTY OFFICIAL

CORNER" IN THE %" IRON ROD WITH THE FOLLOWING WITNESSES:

CORNER" IN THE 1/2" IRON ROD WITH THE FOLLOWING WITNESSES: NORTH 31.95' TO COUNTY TAG IN POWER POLE (EAST) NORTH NORTH EAST 58.55' TO COUNTY TAG IN MAILBOX POST (EAST) SOUTH EAST 61.70' TO COUNTY TAG IN BURIED CABLE MARKER SOUTH WEST 70.57' TO COUNTY TAG IN POWER POLE

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

MICHAEL J. ROSSOW
LAND
SURVEYOR
NO.
24615
LAND SURVEYOR

Signed by

Surveyor's Mighigan Licerise No. 24615

Date /2-//-9



ST. CLAIR COUNTY, MICHIGAN OFFICIAL GOVERNMENT CORNER

SURVEY & REMONUMENTATION

MAR 1 5 2000

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

	Located in: COLUMBUS TOWNS	Corner Code # SHIP	
1. Public Land Survey	T 5N R 15E T R	B-13	
2. Property Controlling in Section	S T R		
Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

- 1978, H. KOBS SURVEY L.6, P.105 (FINDS & WITNESSES A % BAR IN MONUMENT BOX) 1974, C. MELCHING SURVEY L.2, P.561 (FINDS & WITNESSES A % ϕ ROD IN MONUMENT BOX & WITNESSES THE SAME)
- 1988, W. AVEY RECORDED DEED L.1201, P.962 (FINDS & WITNESSES A 3" o ROD IN MONUMENT BOX & WITNESSES THE SAME)
- 1995, G. JAMES SURVEY L.14, P.527 (IDENTIFIES MONUMENT BOX, NO WITNESSES & REFERS TO LCRC L.2,
- P.200)
 1988, UNRECORDED SURVEY (REFERS TO CORNER, DOES NOT IDENTIFY NOR WITNESS)
 1990, C. McDANIEL UNRECORDED SURVEY (REFERS TO CORNER, DOES NOT IDENTIFY NOR WITNESS)
- B-1 CASCO TOWNSHIP, T.4N., R.15E., NO CORNER SET BY GLO FOR THIS CORNER
- 1980, G. AVENDT LCRC L.5, P.178 (WITNESSES NORTH 1/4 CORNER OF SECTION 6, FINDS A 3/2" PIN IN MONUMENT BOX)
- 1955, J. LEHNER UNRECORDED SURVEY & DESCRIPTIONS (IDENTIFIES & USES A "FOUND IRON" IN BOX) 1990, G. JAMES UNRECORDED SURVEY (IDENTIFIES A "MONUMENT BOX" & WITNESSES THE SAME)
- (0) 1982, ANDERSON, ECKSTEIN, WESTRICK UNRECORDED SURVEY (IDENTIFIES & USES A "FOUND IRON" IN BOX)
- 1942, OLD ST. CLAIR COUNTY SURVEYORS RECORD (IDENTIFIES A 1 1/2" PIPE AS CORNER & WITNESSES THE SAME RECORDS NO OFFSET TO SOUTH 1/4 CORNER OF SECTION 31, COLUMBUS T.5N, R.15E.)
 1980, G. AVENDT JR. UNRECORDED SURVEY (FINDS, USES & MEASURES TO A 3/2" PIN IN MONUMENT BOX,
- NO LOCAL WITNESSES RECORDED)
- 1986, R. KREGER, UNRECORDED SURVEY (FINDS A 1" BAR IN MONUMENT BOX & WITNESSES THE SAME) 1991, R. KREGER, ST. CLAIR COUNTY ROAD COMMISSION FIELD BOOK OF WITNESSES (REMOVES & WITNESSES & REPLACES A 3/2" BAR IN MONUMENT BOX)