

ST. CLAIR COUNTY, MICHIGAN OFFICIAL GOVERNMENT CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY & REMONUMENTATION

MAR 1 5 2000

SECTION

CLERK REGISTER ST. CLAIR COUNTY RECEIVED FOR RECORD

DEC	22	1999	800 Am
LIBERP	GE	Time	O Am
Mary PA	<u>ر بر ر</u>	un	,
MAR	ILYN OU	NN	

J

Register of Deeds Stamp & File Number

Located In: Corner Code # COLUMBUS TOWNSHIP I-13 T<u>5N</u> R <u>15E</u>

1. Public Land Survey R 2. Property Controlling Т in Section T 3. Miscellaneous Т R Property in Sec.

4. Lot No. _, Recorded Plat Private Claims

I, MICHAEL J. ROSSOW, in a field survey on JULY 21 19_99, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

ABCDEFGHI KLM 3 4 5 6 7 R 9 10 11 12 13

NOTE: Not more than 1 CORNER, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - I-13 COLUMBUS TOWNSHIP, 1817, W. PRESTON SURVEYOR FOR GLO (SET A 2 MILE POST)
 - (A) 1977, C. ALLOWAY LCRC L.4, P.115 (SETS 1/2" CARRIAGE BOLT WITH TEMPORARY WITNESSES -PERFORMED IN 1975)

 - (B) 1998, D. LITTLE LCRC L.9, P.180 (SETS A "T" IRON IN A FOUND MONUMENT BOX & WITNESSES)
 (C) 1998, D. LITTLE SURVEY L.16, P.451 (REFERS TO "T" IRON IN MONUMENT BOX, NO WITNESSES RECITED)
 - 1942, OLD SURVEYORS RECORD (SHOWS NOTHING FOR THIS CORNER)
 - ST. CLAIR COUNTY ROAD COMMISSION PLANS OF 07-07-1993 (INSTALLED MONUMENT BOX WITH NO WITNESSES)
 - 1986, R. KREGER UNRECORDED SURVEY (FOUND "BOAT SPIKE" & WITNESSES THE SAME)
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A "T" IRON IN A MONUMENT BOX IN PAVEMENT OF F.W. MOORE HIGHWAY WITH SUPPORT DATA OF PART OF PART "A" ABOVE WITH THE FOLLOWING WITNESSES: EAST 108.04' TO THE NORTH EAST CORNER OF SECTION 3, T.4N, R.15E. (FOUND IRON ROD IN MONUMENT BQX)(F) NORTH WEST 277.48' TO PK AND CAP IN SOUTH FACE OF DETROIT EDISON POLE (B)

NORTH EAST 139.45' TO PK AND CAP IN SOUTH WEST FACE OF DETROIT EDISON POLE (B)(F) SOUTH EAST 136.77' TO PK AND CAP IN SOUTH FACE OF DETROIT EDISON POLE (B)(F)

NORTH 50.0' TO FOUND "T" IRON (C)

PA 345-1990 PEER COMMITTEE APPROVED_12-15-99

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET A 2" DIAMETER ALUMINUM CAP WITH MAGNET ATTACHED & INSCRIBED *ST. CLAIR COUNTY OFFICIAL CORNER" ON A 1/2" REROD IN PLACE OF FOUND "T" IRON IN MONUMENT BOX WITH THE FOLLOWING WITNESSES:

EAST NORTH EAST 139.95' TO COUNTY TAG IN POWER POLE EAST SOUTH EAST 136.81' TO COUNTY TAG IN POWER POLE SOUTH EAST 68.43' TO COUNTY TAG IN 8" TREE

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL

WEST NORTH WEST 277.45' TO COUNTY TAG IN POWER POLE SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Surveyor's Michigan License No. 24615

OF MICHIG MICHAEL J. ROSSOW LAND SURVEYOR NO. 24615 LAND

BOOK 009 PAGE 323