## SURVEY & ST. CLAIR COUN OFFICIAL GOVERN

## ST. CLAIR COUN

MAR 1 6 1999

## LAND CORNER RECO

NTY, MICHIGAN NMENT CORNER	
RDATION CERTIFICATE Act 74, Mich. P.A. 1970	WCHIC'S

-		of Act 74, Mich. P.A. 197	CHICS
SECTION	i miig nedunement	or Act 74, Mich. P.A. 197	
	Located In:	Corner Code #	- 50 (7)
	St. Clair Township		
<ol> <li>Public Land Survey</li> </ol>	T_5N_R_16E_	<u> </u>	
2. Property Controlling S	TR TR		
in Section S			네 생활을 드로 날뛰다
	TR		
Property in Sec. S	TR		
			Register of Deeds Stamp & File-Humber
4. Lot. No, R	ecorded Plat		ABCDEFGHIJKLM
5. Private Claims		<del></del>	2 6 5 4 3 2
I, John C. Niederhauser_,	in a field survey on Oct	ober 19 .	3
		P.A. 74, Michigan P.A. of	
•		bove were in conformance	
		e current manual of survey	18
instructions of the United	•	e interior, Bureau of Land d/or that the corner points	7
		nance with the rules of the	
Michigan Board of Land			10 20 20 27 25 25
established, re-established	, monumented, re-monum	ented, recovered, found as	11 23 - 23 - 25 - 25 - 25 - 25 - 25 - 25 -
expressed below:			12 31 32 33 34 35 36
MATERIAL CONTRACTOR	200MTD		13
NOTE: Not more than 1 (	COHNER, may be record	ied on this certificate.	
A. Description of original r	monument and accessorie	es and/or subsequent resto	oration:
, ii = uoonpiion = onginan			· <del>- · · · · ·</del>
,	-		eyors Record lists corner witnesses but
			ded a chiseled "X" in pavement, 8.0' east
			ober 1972. John Lansky recovered and
			1, dated May 1975. Warren Avey rember 1990. Clyde McDaniel recovered
		e LCRC Liber 6, page 341,	
	•	,	
B. Description of corner ev	vidence found and/or met	hod applied in restoring or	reestablishing corner:
Found cut "X" 2.0' south of	the centerline of Fred Mo	ore Highway (24' wide con	crete), 8.0' east of a second cut "X" at the
			ously recorded witnesses on recorded
			corners. East to south quarter corner
Section 31, 2,676.62' (R),	2,676.52' (M) and south to	east 1/4 corner Section 1,	, 2,691.65' (R), 2,691.66' (M).
	. *		÷
		•	
C. Description of monume	ent for corner and access	ories established to perpetu	uate locating the position of the corner:
	**************************************		
			ounty Official Corner", placed on a 1/2"
			center of Fred Moore Highway and
			13 of T5N-R15E and A-1 of T4N-R16E.
	"X" in concrete pavement retline of concrete pavements.	τ. ent of Fred Moore Highway	
	ut "X" on top of concrete		•
	The state of the s		Na 2 199
S 30°E 57.02' to PI	K nail with SCC Road Cor	nmission washer in north fa	ace of 6" elm tree. Sec. B, 1998
S 00°E 101.64' to F	PK nail with SCC Road Co	ommission washer in east s	side of 24" maple tree.
· ~ \			
// //	1 20		× %0
Signed by	Linke Vanne		Date December 4 1998