

**ST. CLAIR COUNTY, MICHIGAN  
OFFICIAL GOVERNMENT CORNER**



**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

	Located In:	Corner Code #
1. Public Land Survey	T <u>6N</u> R <u>15E</u>	<u>I-1</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg 1</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED  
 1993 DEC 29 AM 9:00  
 REGISTER OF DEEDS ST. CLAIR COUNTY MICHIGAN  
 Register of Deeds State & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, David J. Little in a field survey on October 6, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 1 corner, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:  
**Post-(Government Surveys)**

Corner not identified on Old Surveyor's Record St. Clair County.  
 Corner Recorded in L.4 P.311 (RLS 7966)

STATE PLAIN COORDINATES  
 N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 ELEVATION \_\_\_\_\_

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Iron with Cap RLS 19835 in Monument Box  
 Corner varified by 1930 Michigan State Highway Department plans

2159A000 12/29/93MSU7 11.00  
~~2159A000~~ 12/29/93SRE7 2.00  
 \*\*0001\*\*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Iron with Cap RLS 19835  
 SW 56.45' to set P.K. and County Tag in NW face of light pole  
 SE 122.17' to set P.K. and County Tag in N. face of D.E.P.  
 NE 109.68' to SW corner of foundation of house #8370.  
 N. 59.92' to set P.K. and County Tag in W. face of 8" Pine.

See attached sketch for additional information.  
 (Corner is on centerline of existing lapeer Road pavement)



Signed by David J. Little  
 Surveyor's Michigan License No. 31596

Date November 20, 1993

PA 345-1990  
 PEER COMMITTEE  
 APPROVED 12-7-93

APPROVED AS AN OFFICIAL GOVERNMENT CORNER BY ST. CLAIR COUNTY:

Signed By: \_\_\_\_\_  
 St. Clair County Land Surveyor  
 Surveyor's Michigan License No. \_\_\_\_\_

Date \_\_\_\_\_  
 LIBER 007 PAGE 154