

**ST. CLAIR COUNTY, MICHIGAN  
OFFICIAL GOVERNMENT CORNER**



LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

	Located In:	Corner Code #/
1. Public Land Survey	T <u>6N</u> R <u>15E</u>	<u>L-1</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg 1</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED  
1993 DEC 29 AM 9:03  
REGISTER OF DEEDS ST. CLAIR COUNTY MICHIGAN  
Register of Deeds Stamp & Filing Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, David J. Little, in a field survey on October 18-20, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

**NOTE: Not more than 1 corner, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

**This Corner was not set in Government Surveys**

**Ford Axle and 1" Iron shown on Old Surveyor's Record St. Clair County.**

**Iron in Monument Box recorded in L.2 P.184 (RLS 19835) of recordation certificates.**

STATE PLAIN COORDINATES

N. \_\_\_\_\_

E. \_\_\_\_\_

ELEVATION \_\_\_\_\_

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**Found Iron with cap RLS 19835**

**Corner on line with NW Corner Section 1 T6N, R15E and the SE Corner Section 36 T7N, R15E.**

**Corner varified with the 1930 Michigan State Highway Department plans.**

2159A000 12/29/93MSSU4 9.00  
\*\*0001\*\*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**Iron with cap RLS 19835**

2159A000 12/29/93SSSE4 2.00  
\*\*0001\*\*

SSW 24.30' to NE Corner of headwall.  
SW 133.72' to set P.K. and County Tag in SW face of D.E.P.  
NW 133.95' to set P.K. and County Tag in SW face of D.E.P.  
NE 114.78' to set P.K. and County Tag in SE face of D.E.P.  
(Corner is on the centerline of existing Lapeer Road pavement)



See attached sketch for additional information.

Signed by David J. Little

Date November 21, 1993

Surveyor's Michigan License No. 31596

PA 345-1990  
PEER COMMITTEE

APPROVED 12-7-93

APPROVED AS AN OFFICIAL GOVERNMENT CORNER BY ST. CLAIR COUNTY:

Signed By: \_\_\_\_\_

Date

St. Clair County Land Surveyor

Surveyor's Michigan License No. \_\_\_\_\_