

**ST. CLAIR COUNTY, MICHIGAN
OFFICIAL GOVERNMENT CORNER**



**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

	Located In:	Corner Code #
	Wales Twp.	
1. Public Land Survey	T <u>6N</u> R <u>15E</u>	<u>M-4</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg. 1</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED
 REGISTER OF DEEDS
 ST. CLAIR COUNTY
 1993 DEC 29 AM 9:03
 Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	16		17		18		19		20		21		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, John R. Lansky in a field survey on Sept. 27-Oct. 1, 1993
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 1 corner, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. Post-- Original Gov't Survey
2. Nothing listed on Old Surveyor's Rec. St. Clair Co
3. Iron Per Certificate L.2 P.221

STATE PLAIN COORDINATES
 N. _____
 E. _____
 ELEVATION _____

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found Iron Rod



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Iron Rod w/cap (Unreadable)
 S.W. 98.00 ft. Found Spike/Cap RLS 18659 in D.E. Pole
 South 3.6 ft. to North Edge of Asph Pav't. (Sparling Rd.)
 N.E. 23.97 ft. Set PK Nail & tag in Gate Post 2159A000 12/29/93MSU4 9.00
 N.W. 38.00 ft. Set " " " in D.E. Pole **000J**
 2159A000 12/29/93SRE4 8.00
 See attached sketch for additional information. **000J**

Signed by John R. Lansky Date October 6, 1993
 Surveyor's Michigan License No. 18659

PA 345-1990
 PEER COMMITTEE
 APPROVED 11-23-93

APPROVED AS AN OFFICIAL GOVERNMENT CORNER BY ST. CLAIR COUNTY:
 Signed By: _____ Date _____
 St. Clair County Land Surveyor
 Surveyor's Michigan License No. _____