

**ST. CLAIR COUNTY, MICHIGAN
OFFICIAL GOVERNMENT CORNER**



LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Located In: CLYDE Corner Code # _____

1. Public Land Survey	T <u>7N</u> R <u>16E</u>	<u>A-13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg 1</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED
REGISTER OF DEEDS
ST. CLAIR COUNTY
MICHIGAN
1993 DEC 29 AM 9:03
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, David J. Little, in a field survey on October 21-22, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 1 corner, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
Post-(Government Surveys)

**Monument Box listed on Old Surveyor's Record
St. Clair County (T7N, R16E)
Stone Listed on Old Surveyor's Record (T7N, R15E)

No Certificate filed on this corner.**

STATE PLAIN COORDINATES

N. _____

E. _____

ELEVATION _____

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found 1" Iron in Monument Box 20" below road surface.

Corner verified with 1930 Michigan State Highway Department plans.

2159A000 12/29/93HSSU# 9.00
0001
2159A000 12/29/93SSRE# 2.00
0001

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
1" Iron in Monument Box.

**NW 76.85' to set P.K. and County Tag in D.E.P.
SE 83.90' to Set P.K. and County Tag in 36" Oak.
SW 76.45' to set P.K. and County Tag in D.E.P.
NE 120.70' to set P.K. and County Tag in D.E.P.
(Corner is on centerline of existing Lapeer Road pavement)**

Corner Common to SE corner Section 36 T7N, R15E.

See attached Sketch for additional information.



Signed by David J. Little
David J. Little 31596
Surveyor's Michigan License No. _____

Date November 23, 1993

PA 345-1990
PEER COMMITTEE

APPROVED 12-7-93

APPROVED AS AN OFFICIAL GOVERNMENT CORNER BY ST. CLAIR COUNTY:

Signed By: _____
St. Clair County Land Surveyor

Date

Surveyor's Michigan License No. _____