SUMVET G REMONUMENTATIO!

> JUL 1 4 1997 COMMISSION .

ST. CLAIR COUNTY, MICHIGAN OFFICIAL GOVERNMENT CORNER

LAND CORNER RECORDATION CERTIFICATE

		Filing Req	uirement of Act 74, Mich. I	P.A. 1970	REG	IIC
		Located in: Greenwood Tow	Corner Code ##		. G. S.	
	Public Land Survey	T 8N R 15E T R T R			I AN 8: 01 TOF DEEDS	
3. I	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R		Register of De	eeds Stamp & I	
4. 5.	Private Claims			2 G 3 4 7	C D E F G	H I J K L M
in lir curre Mana abov Coue	ereby certify that under re nes if and 2 above were i ent manual of survey instr agement or by a decree of re were in conformance w	equirements of P.A. 74, Michigan in conformance with regulations ructions of the United States De f a Court of Law and/or that the co rith the rules of the Michigan Boa	P.A. of 1970, the corner points men s and rules therefore as required epartment of the Interior, Bureau o orner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree-monumented, recovered, four	ationed 6 18 19 19 19 19 19 19 19 19 19 19 19 19 19		-22 - 23 - 24 - 25 - 25 - 25 - 25 - 25 - 25 - 25
NOTE: Not more than 1 corner, may be recorded on this certificate.				12	32 33	-343536
	Joseph Wampler se	t a wood post in 1822 a	and/or subsequent restoration: as the original governme ld notes. Reference cor			

R15E and M-13 of T9N-R14E. Old county surveyor's record listed a 3/4" pipe. C. Alloway recovered and recorded a P.K. nail, L.C.R.C. Liber 4, Page 176. C. McDaniel recovered a P.K. nail and set and recorded a R.R. spike L.C.R.C. Liber 6, Page 335. J. Niederhauser found and recorded a R.R. spike L.C.R.C. Liber 6, Page 391. Also referenced BMJ surveys dated 6-1-1989, 11-11-1991 and 8-5-1993, Collins surveys 11-23-1979 and 7-10-1974; Alloway surveys dated 9-14-1975 and 2-10-1976.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. spike on centerline of Metcalf Road pavement east and west and Cork Road to the south and an old fence line to the north. Verified corner from found witnesses on recorded L.C.R.C. Liber 6, Page 391. Replaced R.R. spike with a 1/2" iron rerod and 2" diameter aluminum cap inscribed "St. Clair County Official Corner" set in a new monument road box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 2" diameter aluminum cap with a magnet attached and inscribed "St. Clair County Official Corner" on a 1/2" iron rerod in a new monument road box. This corner marks the intersection of four (4) townships. For additional information reference corners M-1 of T7N-R14E, A-1 of T7N-R15E and M-13 of T8N-R14E.

N. 29.78' to set P.K. nail with county remon. tag in east side of power pole.

N.E. 99.81' to set P.K. nail with county remon. tag in south side of 8" Boxelder tree.

S.S.E. 101.94' to set P.K. nail with county remon. tag in west side of 10" Ash tree.

S.S.W. 93.49 to set P.K. nail with county remon. tag in east side at the northeast torner of a wood

East 2542.62' to the north quarter corner of Section 6, T7N-R15E. South 2458.30' to the west quarter corner of Section 6, T7N-R15E. PA 345-1990

24608

PEER COMMITTEE

JOHN C NIEDERHAUSER LAND ERED IND

Surveyor's Michigan License)No.