NOV 0 4 1997

LAND CORNER RECORDATION CERTIFICATE

For corners in Commission	Filing Requirement of Act 74, Mich. P.A. 1	970 LIBER 4 PAGE 342
ST. JOSEPH Located In: (County) LEONIDAS TWP. 1. Public Land Survey T_ T_	Corner Code # 5 R 9W	STATE OF MICHIGAN ST. JOSEPH COUNTY FILED 20 MAY 97 11:56 A.M.
2. Property Controlling S T	R	CYNTHIA JARRATT REGISTER OF DEEDS Register of Deeds Stamp & File Number
requirements of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules therefore as n United States Department of the Interior, Bureau of L that the corner points mentioned in lines 3, 4 and 5 a	y on <u>MAY 8</u> , 19 <u>97</u> do hereby state that under corner points mentioned in lines 1 and 2 above were in equired in the current manual of survey instructions of the and Management or by a decree of a Court of Law and for above were in conformance with the rules of the Michigan burt of Law; established, re-established, monumented,	A B C D E F G H I J K L 2 6 5 4 3 2 1 1 3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13
Description of original monument and acce	ssories and/or subsequent restoration:	11 12 31 32 33 34 35 36
GLO 9" BEECH = N18°E 15 LKS. 9" BEECH = S83°W 27 LKS.	1865 SURVEY IN 1/116 STAKE SET FROM OLD BEARINGS	1926 ROAD SURVEY BY MCCOY SHOWS STONE IN N-S CENTERLINE AND A SHORT DISTANCE NORTH OF E-W CENTERLINE OF ROADS
B. Description of corner evidence found and/or DUG WITH COUNTY ROAD COMMISS FOUND LARGE STONE (KNOCKED O' INTER. OF ROADS SET STONE UPRIGHT	VER) 4' NORTH OF & RATIFI IN ACC ON_A	ED BY PEER GROUP CORDANCE WITH P.A. 345 1A
C. Description of monument for corner and access of 5/8" X 12" BAR WITH STD. SW COR. RR RAIL POST = \$43°E NW COR. RR RAIL POST = \$40°W N & W IN SE SIDE P.P. = N49°E N & W IN SW SIDE 60" SYCAMORE Signed by	51.58' 48.63' 49.12' = N14°E 129.48'	WAYNE A. MOSTROM PROFESSIONAL SURVEYOR No. 14100 PROFESSIONAL 17/97