LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 18 T. 5 S., R. 10 W.	A-5, C-5 S7. Joseph C
2. PROPERTY CONTROLL- ING IN SECTION——, T. —— S., R. —— W.	37. 33
3. MISCELLANEOUS N. E. PROPERTY IN SECTION T. T. S., R. W.	·
4. LOT NO, RECORDED PLAT	
5. PRIVATE CLAIMS	REGISTER OF DEEDS STAMP AND FILING NUMBER
Donald L. Bissell	y that under requirements of P.A. 74, Michigan P.A. of 1970,
the corner points mentioned in lines 1 and 2 above were, in a field survey on	
•	
B. Description of corner evidence found and/or method applied A-5 Mon. Box in Pav't. C-5	n restoring or re-establishing corner: Found: Pointed stone with witnesses
with 3/8" Iron Pipe	West 17.15' p.k. nail in anchor post North 26.55' p.k. nail in anchor post S 29 W. 12.15' p.k. nail in 8" hedge N 76°W. 12.70' p.k. nail in 12" hedge N 34°E. 23.70' p.k. nail in 12" hedge Set: 4" x 36" concrete monument.
C. Description of monument for corner and accessories establishe	d to perpetuate locating the position of the corner:
A-5 Mon. box with 3/8 iron pipe C-5 S 85°E., 40.75', 36" Oak S 52°E., 36.41', Power pole S 22°E., 72.43', Butternut N 60°W., 66.63', Anchor pole	4" x 36" Concrete mon. with alum. cap West 17.15' P.k. nail in anchor post North 26.55' p.k. nail in anchor post S 29°W, 12.15' p.k. nail in 8" hedge N 76°W, 12.20' p.k. nail in 12" hedge N 34°E, 23.70' p.k. nail in 12" hedge.
SIGNED BY	DATE
SURVEYOR'S MICHICAN REGISTRATION NO	(SEAL)
FOR STATE AND UNITED STATES AGENCIES:	
SIGNED BY	DATE
APPROVED AND SIGNED BY LONG TRUE	LL DATE 7-12-83
MICHIGAN REGISTERED LAND S	JAVETUR (SEAL)
SURVEYOR'S MICHIGAN REGISTRATION NO 1865	5