

SURVEY &
REMONUMENTATION

MAY 07 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 4 PAGE 288

For corners in
St. Joseph Located in:
(County)

Corner Code #

1. Public Land Survey T 5S R 10W G-9
 T ___ R ___
 T ___ R ___
 T ___ R ___
2. Property Controlling S ___ T ___ R ___
 in Section S ___ T ___ R ___
3. Miscellaneous S ___ T ___ R ___
 Property in Sec. S ___ T ___ R ___
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

STATE OF MICHIGAN
ST. JOSEPH COUNTY
FILED

30 DEC 96 2:00 P.M.

CYNTHIA JARRATT
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Donald C. Andrews, in a field survey on October 10, 1996, do hereby certify that under requirements of P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-9
GLO Post

R.E. Sayers found Boat spike

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-9
found 12" long bridge spike down ± 8 ". Removed spike and dug 3 feet below surface. Nothing else found.

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON May 13, 1996
Wm CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9
Set Alum. Capped 5/8"x24" iron in monument box: 1) PP N60°E 28.69', 2) 10" Oak N5°E 28.69', 3) 4" Oak S45°E 38.79', 4) 6" Cedar S60°W 46.06'.

Signed by Donald C. Andrews
Donald C. Andrews, P.S.

Surveyor's Michigan License No. 33967



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS., JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD-PROCESSING

REMONUMENTATION

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

LIBER 4
PAGE 288

12/23/96