·			RECORDATION			K	DACE	23				
For corners in Park Townshi	Р	ing Keganei	nent of Act 74, W	IICII. P.A. 13.	/ UL_LD	in war			MICHIE	ian		
St. Joseph County (County)	Located In:	Corner	Code#				ST.	JOSEF FILE	PH COUN ED	!TY		
1. Public Land Survey	T <u>58</u> T <u> </u>		E-9 URVEY & NUMENTATIO	N			CYN	ITHIA L	10:14 JARR OF DEE	ATT	H	
 Property Controlling in Section Miscellaneous Property in Sec. 	S T S T	R JA R JA R	N 3 1 2001 ECTION		R	egist	er of C	eeds (Stamp	& File	Numl	ber
					A	вс	D E	F (3 H	i J	Κŧ	. N
4. Lot No, Reco 5. Private Claims	rded Plat	 			2	6	-5-	_4_	3-		1	
					3 -		-	- -				
I. <u>David W. Mostrom</u> , in a field su. P.A. of 1970, the corner points mention required in the current manual of su Management or by a degree of a Courconformance with the rules of the Miclestablished, monumented, recovered, for	ed in lines 1 and 2 above rvey instructions of the I t of Law and/or that the o nican Board of Land Sur	were in conformance United States Depa corner points mentic vevors or by a Dec	e with regulations and rules riment of the Interior, Bur oned in lines 3.4 and 5 at	therefore as reau of Land bove were in	4	8	-17	9 16 	15-22-	11-	1. 2.	2— 3— 4—
NOTE: Not more than 2 corners	, all in the same tow	n and range, mag	y be recorded on this o	certificate.	93	0	-29	28	27	26	2	<u></u>
(E-9) CORNER COMMON TO	O SECTIONS 20,	21, 28, 29 PAI	RK TOWNSHIP		11		-			ert	+ 1	\dashv
A. Description of orlginal mor	nument and access	ories and/or su	bsequent restoratio	n.	12 3	1	-32	_33	<u>3</u> 4	35_	34	5—
<u>GLO</u> 8" W. OAK = N48°W 1.32' 6" W. OAK = S31°W 18.48' 1879 SURVEY IN BOOK A, PAGE	÷ 304	STONE 14" B. WALN	Y IN BOOK B, PAGE 1 UT = N38°E 30.20' UT = N71°E 73.92'	<u>110</u>		l Door	W.O. D.					
SET 14" X 8" X 6" STONE MARKI FROM THE REMAINS OF THE O 3" WALNUT = N38°E 30.86' 8" WALNUT = N71°E 74.58'	ED Ŧ	1972 SAYER: BOX OVER S 30" WALNUT FENCE COR W. OAK = SE	TONE = NE 30.15' NER = NW 34.35'	1979 L FOUNT 30" WA 40" OA 4" CED	STO LNUT K = S4	VE IN = N40 5°E 40	MON. 1 0°E 32.0 9.45'	30X	ğ			

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND NOTCHED STONE 9" DEEP IN MONUMENT BOX 36" WALNUT = N40°E 30.86" 48" OAK = \$45°E 49.45"
10" CEDAR = \$10°W 52.69"
CENTERLINE MOOREPARK ROAD = SOUTH 1.5"
SET 5/8" X 6" IRON BAR WITH STD. CAP IN CONCRETE OVER STONE IN MONUMENT BOX



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 6" IRON BAR WITH STD. CAP IN MONUMENT BOX SW CORNER HOUSE FOUNDATION = N25°E 88.15°
N & W IN NW SIDE OF 40" WALNUT = N37°E 31.08'
N & W IN E. SIDE OF 10" CEDAR = N12°W 52.65'
N & W IN E. SIDE OF 11" CHERRY = S27"W 32.98'
N & W IN SW SIDE OF 50" OAK = S52°E 49.41'

RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 ON MAR. 13 2000 CO. REPRESENTATIVE

Signed by J.JW. US		David W. Mostrom	С
Surveyor's Michigan License No	32339		

REMONUMENTATION

March 23, 2000

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 18, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995