THE WASTER AN 2 4 1996 LAND CORNER RECORDATION CERTIFICATE JAN 2 4 1996

201 & 2 MAL	6 CORNER BI	ECORDATION CERTI	A 1970		
مراد الله الله الله الله الله الله الله ال	LAND CONTERNE	nt of Act 74, Mich. P.	A, 1910	F	ILED
COMMISS	Located In:	Corner Code =##		Dec 7	10 48 M 193
ST. JOSEPH FLOWERFIELD TWP. Public Land Survey	TR TR TR	<u>K-7</u>		REGIST ST. JO	P. Lauctit TER OF DEEDS SEPH OF MICH
n and Collinguing	TR		Registe	r of Deeds Star	mp & File Number
in Section S 3. Miscellaneous S	TR	1	2	A B C D E	F.G.H.J.K.L.M
Property in Sec. 4. Lot No, Reco 5. Private Claims			3	8-1-8-1	-9101712-1
I. WAYNE A. MOSTROMO do hereby certify that under require in lines 1 and 2 above were in conformation of survey instruction of the conformation of the certificate.	ons of the United States Depart ourl of Law and/or that the corni- the rules of the Michigan Board established, monumented, re- eners, all in the same town a	er points mentioned in line of Land Surveyors or by a monumented, recovered and range, may be recovered.	Decree of a tound as	6 18 17 7 8 19 20 9 10 30 29 11 12 31 32	-16 - 15 - 14 - 13 21 - 22 - 23 - 24 28 - 27 - 26 - 25 28 - 33 - 34 - 35 - 36 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 35 - 36 - 36
NOTE: Not more this certificate.	d accessories a	ind/or subsequent rest	oration:		
1962 BY ROAD COMM 1/2 " PIPE DRIVEN IN PLACE OF 1" ROD PLACED BY ROD PLACED BY	1972 BY R.G. S (SHOWS TRAVERS AROUND E1/2 SE STOP SIGN = SI STOP SI STOP SIGN = SI STOP SI STOP SIGN = SI STOP S	AYERS E C.) 50W 35.80 150W 35.80 150W 45.8 P.P.= 50W 510WAPLE 10WAPLE 10WAPL	" OR I" PIPE	P.P. = \$25°W	59.35
FORMER SURVEY MON. BOX 27" BLK. OAK = N18 27" BLK. T N32°E	ABOVE BI		1	on corner:	

1962 BY ROAD COMM

1/2 " PIPE DRIVEN
IN PLACE OF 1"
ROD PLACED BY
FORMER SURVEYOR IN
MON. BOX
27" BLK. OAK = N18°W 77.9'
DBL. OAK = N32°E 51.9'
TELE. POLE = S21°E 52.8' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" PIPE IN MON. BOX P.P.=S25°W 90.5 4" MAPLE N60°E 72.10" P.P. = N60°W 59.351



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

SET STD. CAP OVER PIPE IN MON. BOX SW COR GARAGE = N38°E 125.96' NE COR HOUSE = N25°W 155.68'
NE COR HOUSE = N25°W 155.68'
P.P. = S25°W 90.50' (N&W IN E. SIDE POLE)
P.P. = N60°W 59.35 (N&W IN E. SIDE POLE) APPROVED BY PEER GROUP AS BEST AVAILABLE EVIDENCE OF CORNER

Dale 11/17/93 Signed by _____ Surveyor's Michigan License No. 14100

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

10