LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Mendon Towship	Filing Requirement of Act 74, Mich. P.A	LIBER 6 PAGE 65
St. Joseph County Located In:	Corner Code #	STATE OF MICHIGAN
(County)	Collies Code #	ST. JOSEPH COUNTY FILED
1. Public Land Survey T5	S R <u>10W</u> <u>C-13</u> R	18 AU6 2000 10:32:30 AN
<u> </u>		
2. Property Controlling S T in Section S T	R SURVEY & R	CYNTHIA L. JARRATT REGISTER OF DEEDS
3. Miscellaneous ST_	R	•
Property in Sec. ST_	R JAN 31 2001	Register of Deeds Stamp & File Numbe
4. Lot No, Recorded Plat	SECTION	ABCDEFGHIJKL
5. Private Claims	2000 11001	2 - 6 - 5 - 4 - 3 - 2 - 1 -
		3
i Duidlat Madana in a fald aureas an Assesse O	20 00 do state that under new thorough of D.A. 74 Michiga	4 7 8 9 10 11 12
P.A. of 1970, the corner points mentioned in lines 1 and 2:	_ 20_00_ do state that under requirements of P.A. 74, Michiga above were in conformance with regulations and rules therefore a	s
Management or by a degree of a Court of Law and/or that	the United States Department of the Interior, Bureau of Lan tithe comer points mentioned in lines 3, 4 and 5 above were in	7 7 7
conformance with the rules of the Michigan Board of Lar established, monumented, recovered, found as expressed	id Surveyors or by a Decree of a Court of Law, established, re- below:	8 19 20 21 22 23 24
•		9
·	e town and range, may be recorded on this certificate.	10 30 29 20 27 20 25
(C-13) SOUTHEAST CORNER SECTION (1, MENDON TOWNSHIP	11
A. Description of original monument and ac	cessories and/or subsequent restoration:	13
GLO 9" W. OAK = N88 1/2° E 48.84'	1955 PLAT OF RIVERVIEW SHORES *PLAT SHOWS JOG DISTANCE TO	
9" W. OAK = N70°W 72.6'	NOTTAWA TOWNSHIP CORNER IS	
*JOG TO (C-1) T6S, R10W = WEST 62.7'	WEST 62.70'	<u>1994 SURVEY BY MOSTROM</u> "FOUND 1⁄2" IRON BAR
1864 SURVEY IN BOOK A, PAGE 88 STONE FROM OLD BEARING STUMPS	1973 LCRC IN BOOK 1, PAGE 17 *SET IRON BAR ON LINE & DOUBLED	'36" STUMP = N70°E 59.79' '10" PINE = N40°E 83.5'
1889 SURVEY IN BOOK A, PAGE 594		'36" OAK = \$70°E 103.5' 'NOTTAWA TOWNSHIP CORNER ≃ WEST 62.7'
CORNER USED ON SURVEY BUT NOT LABELED OR WITNESSED	BASED ON SURVEY IN BOOK A, PAGE 88	
	30" CHERRY = NE 39.40'	RATIFIED BY PEER GROUP
	*36" OAK.= E-NE 59,79' 12" PINE = 70.68'	IN ACCORDANCE WITH P.A. 345 ON AUG. 14 , 2000
		May CO. REPRESENTATIVE
B. Description of corner evidence found and	d/or method applied in restoring or reestablishing	g corner:
CORNER FALLS IN LINE WITH PROJ. OF NOTTAWA TOWNSHIP CORNER (STONE STUMP REMAINS OF OLD 36" OAK = N70 12" PINE = N40°E 83.5' 36" OAK = S70°E 103.5'	ANGEVINE ROAD TO THE NORTH & 7' NOR' EIN MONUMENT BOX) = WEST 62.77' I°E 59.79'	OAD IN BLACE OF WILLDON BAR
C. Description of monument for corner and 5/8" X 24" IRON BAR WITH STD. CAP IN N & W IN NORTHWEST SIDE OF ANCHO & W IN NORTHWEST SIDE OF 10" OAK & W IN SOUTHEASTERLY SIDE OF 12" N & W IN WEST SIDE OF 20" PINE = S23"	R POST = S82°W 94.38' = S80°W 94.38' PINE = N45°E 83.35' W 196.48' DAY MOS	
1 & W IN SOUTH SIDE OF 8" CLUSTER =	N74°E 82.71'	SSIONAL) = =