NOV 1 5 1994

004 PG 054

FILED

LAND CORNER RECORDATION CERTIFICATE COMMISSION

SEP 29 4 54 PM 194

For corners in				970		T.	piodi		الم. ر	بمل	ته	u		
<u>s</u>	County)	·	Locate	ed In:	Corner Code :##			!	RECIS ST. J	TER	0F (DEE	DS CH	
1.	Public Land Survey			S R 10W										
				R										
2	Dramanti Oantuilli	٠,	<u>T</u>	R	* ****									
۷.	Property Controlling in Section	S	!	R										-
3.	Miscellaneous	» <u> </u>	! T	R										
•	Property in Sec.	s	'	R		Registe	r of	Dee	ds St	amp	& Fi	le N	lum	ber
4.	Lot No.								•				·	
5.	Private Claims					#	В	C	D E	F	в н	1 1	J	ĸ
						2	6-		5	_	-3	4	<u> </u> 2 -	
	•		•			3				_	11	_		
						4	_ }_			_			_ 11-	
I, WAYNE A. MOSTROM , in a field survey onSEPT. 8 , 19 94										_Ĭ	ĹΪ		Ï	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the							_	,	,	16		Т		Y
cur	rent manual of survey ins	and rules therefore as required in the artment of the Interior, Bureau of Land	6 L 7	— 18— 	7-	ĺ]	;s-	T	14 				
management or by a decree of a Court of Law and/or that the co				or that the cor	ner points mentioned in lines 3, 4 and 5	8							┪	_
above were in conformance with the rules of the Michigan Boa Court of Law; established, re-established, monumented,			iichigan Board	d of Land Surveyors or by a Décrea of a	9	19 	²	i T	-21— 	22-	十	23 		
exp	ressed below:	, re-establis	hed, mo	numented, re	e-monumented, recovered, found as	_ T	-	1		1		+	1	+
•		corners a	ll in the	sama taun	and range, may be recorded	10	30	2	9	-2'8 	2 ⁷ 7	\top	–2'6– I	+
	on this certificat	e.	(116	same town	and range, may be recorded	11	_	1-	-	+1		+	_	+-
					•	12	3 ⁻ 1	3	2	33	3'4-	+	-3 ' 5	
A.	Description of origina	ıl monumer	and ac	cessories a	nd/or subsequent restoration:	13 🛴							!	
	<u>K-5</u>				,									
	1892 SURVEY -BO	XX A, PA	AGE 58	3	R.R.A.P. = N40°E 41.65	1 10	7 <u>6</u> 1	ıc	D C		1	z	ь	c/.
"CORNER WAS RESET IN REMAINS OF ORIG. GOV'T POST"					R.R.A.P. = N35°W 35.12 52" MAPLE = \$70°E 75.10	MON	1974 L.C.R.C L-3, P-54 MON. BOX 3" DEEP RAIL A.P. = NE 41.65							
ROAD COMMISSION - 1963					14" OAK = \$25°W 68.87"	RA]	IL /	A. P	. =	NW	35	.12	1	
	DROVE 3/4" PIPE BRICK & TILE -	THRU OL	D WOO	D STAKE,					Ξ = = SW) †	
3.	Description of corner	evidence fo	und and	d/or method	applied in restoring or regatablishing									

<u>K-5</u>

FD. 1" X 27" PIPE IN MON. BOX RAIL A.P. = N40°E 41.65 RAIL A.P. = N40°W 35.12

RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 9/12 , 19 94 CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-5 (COR. COMMON TO SEC'S 11, 12, 13, 14)

SET 5/8" X 24" IRON BAR W/STD. CAP IN MON. BOX

S. FACE RAIL A.P. = N40°E 41.65

S. FACE RAIL A.P. = N40°W 35:121

N. FACE RAIL A.P. = \$46°E 36.25'

N & W IN S. SIDE 8" HICK. = N50°W 55.75"

CL RDWY (DIRT) TO N. = 3' EAST CL RDWY (DIRT) TO S. = 2' EAST CL E-W ASPHALT RDWY = NORTH 1'

MOSTROM PROFESSIONAL SURVEYOR No. 14100

Surveyor's Michigan License No. ___

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971