JAN 3 1 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Lockport Township LIBER 6 PAGE 84 Corner Code # St. Joseph County Located In: STATE OF MICHIGAN (County). ST. JOSEPH COUNTY FILFI 1. Public Land Survey T<u>6S</u>R<u>11W</u> 29 NOV 2000 12:10:55 PK R 2. Property Controlling R CYNTHIA L. JARRATT REGISTER OF DEEDS R in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims 2 3 I_David W. Mostrom____, in a field survey on October__, 20_00_ do state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land 5 6 Management or by a degree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in 7 conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-8 established, monumented, recovered, found as expressed below: 9 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 10 26 (B-3) 1/4 CORNER COMMON TO SECTIONS 6 & 7, LOCKPORT TOWNSHIP 11 A. Description of original monument and accessories and/or subsequent restoration: 1971 SAYERS SURVEY 17" W. OAK = \$46°E 15.84' BOAT SPIKE IN MON. BOX " W. OAK = N68°W 46.2" P.P. = NW 43.0' P.P. = NE 59.55' 1978 LCRC IN BOOK 2, PG. 1905 SURVEY IN BOOK B, PAGE 162 R.R. RAIL POST = SE 58.0' 12" BOAT SPIKE IN MON. BOX +'D STONE P.K. IN P. POLE = N55°E 59.54' NO WITNESSES P.K. IN P. POLE = N45°W 42.94' 1975 LCRC IN BOOK 3, PG. 63 **BOX & BOAT SPIKE** NE COR. HSE. FNDTN. = \$45°W 106.59' 1954, 1955, 1961 SURVEYS BY JAY WHITE, JR. P. POLE = N43°W 43' NW COR. TRAIL POST = \$65°E 57.95' CORNER USED BUT NOT LABELED P. POLE = N57°E 59.61' OR WITNESSED 1994 MOSTROM REMON. FOUND 1" X 30" CAPPED IRON PIPE #19847 P. POLE = N43°W 43.0' P. POLE = N57°E 59.54' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 1" X 30" CAPPED IRON PIPE #19847 IN MONUMENT BOX P. POLE = N57°E 59.54' CORNER FALLS IN CENTERLINE OF N. MAIN ST. & 2' NORTH OF CENTERLINE LOVER'S LANE REPLACED CAPPED PIPE WITH 5/8" X 24" IRON BAR WITH STANDARD CAP RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 DN NOV .dòso OO, REPRESENTATIVE 2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 24" IRON BAR WITH STANDARD CAP IN MONUMENT BOX 1 & W 2.0' HIGH IN NW SIDE OF P. POLE = N57°E 60.30'
1 & W 2.0' HIGH IN NW SIDE OF 28" MAPLE = \$40°W 103.18'
1 & W 3.0' HIGH IN W. SIDE OF 22" CEDAR = \$25°W 101.82'
1 & W 3.0' HIGH IN SW SIDE OF P. POLE = N43°W 46.49'

TIRE HYDRANT (TOP NUT) = N58°E 42.47'



inned by DN Ut					
igned by		David W. Mostrom	Date	November 14, 2000	
urveyor's Michigan License No	32339				

REMONUMENTATION

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 18, 1971 REVISED MAY 14, 1975