004 8 042

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Jun 27 12 47 PH 194

Cyptita & Langer

For corners in			REGISTER OF DEEDS
_ST. JOSEPH	Located In:	Corner Code //	ST. JOSTAN 1 WAN
SHERMAN TOWNSHIP		1	
Public Land Survey	T 7SR 10W.	J-11	
	T R		
	T R		
	T R		
2. Property Controlling	S T R		
in Section	S T R	-	
3. Miscellaneous	S T. R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4 1-451-	Recorded Plat		- ARCDEFGHIJKLN
			- ABCDELGHIJKEW
5. Private Claims			

DAVID W. MOSTROM in a field survey on ... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J-11) NORTH 1/4 COR. SEC. 35 T7S, R10W

GLO

W. OAK 22 NORTH 3.00 W. OAK 14 S 5 3/4 W 2.19

SURVEY BOOK A, PG 320

EVIDENTLY FOUND THE ORIGINAL 5" CLUMP MAPLE = N48°E 8.38° POST - NO WITNESSESS GIVEN

SURVEY NO.S-12624 BY RLS NO. 33967

SET BAR & CAP MIDWAY & ON LINE BETWEEN SECTION CORNERS

6" TWIN MAPLE = N25°W 19.34"

3" MAPLE = N20°W 7.251

POST - NO WITNESSESS GIVEN 4" TWIN MAPLE = \$45°W 17.431 SAME WITNESSESS AS Description of corner evidence found and/or method applied in restoring or reestablishing corner: SURVEY NO. S-12624

10

12

CORNER RECORDATION BOOK, PG. 209

SAME WITNESSESS AS SURVEY NO.S-12624

CORNER RECORDATION BOOK 3,PG 231

FOUND CONC. MONUMENT SAME WITNESSESS AS

(J-11)

POST FALLS 1.51 FOUND 2' LONG ORIGINAL WOOD POST BETWEEN 2 OLD ANCHOR POSTS IN MARSH. WEST OF OLD FENCELINE RUNNING SOUTH AND FALLS IN E-W FENCELINE REMAINS. ALSO FOUND STAKE 22.77' EAST OF POST AS SET IN SURVEY IN BOOK A, PG 320 WHEN THE N-S 1/4 LINE POSTSUHIVEY \$54°W 15.3 FROM THE CONC. MONUMENT RECORDED IN BOOK 3, PG. 231. WAS RUN.

REMONUMENTATION

AUG 3 1 1994

COMMISSION

RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 NOV. B , 1993 2CO. REPRESENTATIVE

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J-11)

PLACED STANDARD CAP ON 5/8" X 80" REBAR INSIDE 1 3/4" X 5' LONG PIPE OVER ORIGINAL POST FOUND IN MARSH

Date

PK & SHINER 2' HIGH IN W. SIDE OF 12" MAPLE = N24°E 8.34"

PK & SHINER 3' HIGH IN N. SIDE OF MAPLE CLUSTER = \$78°E 17.56'

CONC. MONUMENT = \$54°E. 15.301

PK & SHINER 3' HIGH IN W. SIDE OF 8" MAPLE = \$18°E 61.60'
PK & SHINER 2.5 HIGH IN S. SIDE OF 6" MAPLE CLUSTER = \$87°W


Signed by

DAVID W. MUSTROM

MAY 20, 1994

Surveyor's Michigan License No.

32339



DAVID W.