1997

A STATE OF THE STA

I AND CODNED DECC

		quirement of A			'n	,						
For corners in	ŭ	•	·	1	LIBE	R 4	PAGE	317	•			
ST. JOSEPH Locate	ed In:	Corner Code #										
(County) FLORENCE TWP. 1. Public Land Survey	T <u>7S</u> R <u>11W</u> TR TR	<u>E-6</u>	 					TE OF JOSEP FI				
2. Property Controlling S	TR		_				17 F	far 97	9:37	A.M.		
in Section STR					CYNTHIA JARRATT							
3. Miscellaneous S Property in Sec. S	TR TR TR TR TR		<u> </u>		R	egiste	RE	GISTER eds St	OF D	EEDS	Num	ber
4. Lot No, Recorded Plat			<del></del>		А	в с	נים:	E 7 (	3 H	I	JК	L
5. Private Claims					2 -	- 6		4	3-		2 —	- 1 -
					3		_	<del>                                     </del>	$\vdash$	-		-
I, DAVID W. MOSTROM, in a field requirements of P.A. 74, Michigan P.A. of	id survey on FE	3. 21, 19 <u>97</u> de	o hereby state that u	nder re in	4 —	- 7	— ģ—	—وٰ — ا	10-	+1	<u></u>	-1'2- 
conformance with regulations and rules there United States Department of the Interior, Bu	efore as required in th	e current manual of :	survey instructions o	f the	5 -	-18-	17	16	15-		4	13-
that the corner points mentioned in lines 3, Board of Land Surveyors or by a Decree	4 and 5 above were i	n conformance with	the rules of the Mich	igan	7	$\mathbb{H}$			1			
recovered, found as expressed below:		,	•		8	-1 <sup>9</sup>	2 <sup>l</sup> 0 	2 <sup>1</sup> 1	22-	+-7	!3—— 	2 4 
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				9	-30		-28-	27		6	25-	
on this certificate.					11	$\overline{+}$						+
					12	-31	3 <sup>1</sup> 2	—3 <sup>'</sup> 3—	34		5 	-3 <sup>'</sup> 6- 
A. Description of original monument a	and accessories ar	nd/or subsequent i	restoration:		131—			11	1 1.	/		
(E-6) & CORNER COMMON TO S												
GLO		COMMISSION						BK :			_	
8" BURR OAK = \$18°W 34.32° 8" BURR OAK = \$10°E 14.52°	35" WHITE 20" BLACK 36" BURR		50.2' 40.6'		NE C	OR.	SEC.	PE IN N : S :	2657	.90'		
B. Description of corner evidence for	und and/or method	l applied in restori	ng or reestablishin	ıg corn	er:			فحو	SATE	OF	WICH,	C
(E-6)								# *		AVII	OW.	Y
FOUND 3/4"X11" PIPE OVER STONE 14" DEEP IN MON. CORNER FALLS IN CL OF SEVISON RD. ALL 1963 ROAD COMM. WITNESSES ARE GONE CORNER FALLS 3'± SOUTH OF TREELINE PROJ. TO EAST						'±)	,	* LICENS	PRO			- 1
								***	PRO	FESS	10NA	ري روي
									700	WHAT	Mile.	-
C. Description of monument for corne	d	actablished to not	rnotuato locatina t	ha nne	ition e	of the	corner					
(E-6) 1/4 CORNER C												
SET 5/8"X10" IRON N&W IN E. SIDE OF	BAR W/STD.	CAP IN CO					MON.	вох	•			
N&W IN NE. SIDE OF N&W IN E. SIDE OF N&W IN W. SIDE OF 3/4" PIPE = WEST 2	P. POLE = 33' OAK = P. POLE =	S40°E 44 N05°W 25:	4.81' 2.10'	IN	ACC	ORD MAR	ANCE	ER G WITH	∃Р.А 1;	. 34 9 <i>97</i>	,	
Signed by J-DW M	DAV	ID W. MOST	rrom Date					1997		:		
Surveyor's Michigan License No	32339				, ,	: 4.5	· •					