LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

		\bigcirc			_
,	SURVEY & ATION REMONUNENTATION APR 10 1995 ANISSION	-	•		
	For corners in ST. JOSEPH CONTRIBUTION (County) 1. Public Land Survey				
•	SULME OF			LIBER 4 PAGE 73	
	10193° 1019	, LAND CORNE	R RECORDATION CERT	4-1-4 ,	
	HIL APRIMISSION	Filing Require	ement of Act 74, Mich. P		
	For corners in				
	ST. JOSEPH	Located In:	Corner Code ≠≠	STATE OF MICHIGAN ST. JOSEPH COUNTY	
	Public Land Survey	т <u>7S</u> п <u>9W</u>	E-4	FILED	
	1. Public Land Survey	T R		6 DEC 94 4:31 P.M.	
;	•	T R		0 DEC 77 4.01 1.11.	
		T R		CYNTHIA JARRATT Register of Deeds	
		T R			
	Property in Sec. S	TR		Register of Deeds Stamp & File Number	
	4. Lot No, Recorded P	lat	-	ABCDEFGHIJK	
	5. Private Claims				֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓
				3	
. '	HAVAIT & MOCTDOM		1111 V 25 0 <i>h</i>	4 - 7 - 1 - 6 - 9 - 1 - 10 - 1 - 11 - 1	 -1 2
. ;	I. WAYNE A. MOSTROM in a field do hereby certify that under requirements of	of P.A. 74, Michigan P.A. (of 1970, the corner points menti	ioned 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1
	in lines 1 and 2 above were in conforman current manual of survey instructions of the	e United States Depart	ment of the Interior, Bureau of	Land 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<u> </u>
	Management or by a decree of a Court of La above were in conformance with the rules of			enta IIIIIII	-2+
	Court of Law; established, re-establishe expressed below.	ed, monumented, re-m	nonumented, recovered, four	nd as 10 30 29 28 27 26	25_
	NOTE: Not more than 4 corners, all	in the same town an	d range, may be recorded	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	+
	on this certificate.			12 31 32 33 34 35	-d6
	A. Description of original monument	and accessories and	Vor subsequent restoration		
	<u>E-4</u>			· · · · · · · · · · · · · · · · · ·	- \
	GLO	1870	SURVEY BY GARDNE	ER L.C.R.CL-2, P-27 (197	<u>ر د</u>
. ,	12" Y.O. = S1°E 9.85			SET 1/2" IRON BAR	
r, i	13" Y.O. = NORTH 10.		NG TREE	A.P. = N30°W 35.55° PK. IN A.P. = S34°W 32	ı
				ST. SIGN = $545^{\circ}E$ 38.8	
				•	
į	B. Description of corner evidence for	und and/or method a	pplied in restoring or reest	ablishing corner:	
	<u>E-4</u>				
	FD. REMAINS OF OLD S ABOUT 1.3' NW OF IRO			ARSH LEVEL PER 1870 SURVEY NALLY	
				•	
	•		i	RATIFIED BY PEER GROUP	
• •			ļ	IN ACCORDANCE WITH P.A. 345	
,			L.	ON AUGUST & ,19 <i>94</i> LULLA CO. REPRESENTATIVE	
•			•		
•					
	C. Description of monument for corne			cating the position of the corner:	
	E-4 (1/4 CORNER BET SET 5/8"X24" THROUGH			48" DEEP	
	ALSO SET 5/8"X24" BA	R & STD: CAP	OVER ABOVE POIN	NTS & SET MON. BOX @ ROAD LE	۷E
	CL N. END CULVERT = 5/8"X24" IRON BAR =			OF MO	
	N & W IN S. SIDE 24"	TREE = N70°	W 105.95 ¹	THE HICH	
•	N & W IN NE SIDE 12" CL N-S RDW = E 10',			WAYNE A. MOSTROM	Ŀ
		_		PROFESSIONAL SURVEYOR C	
1	$\sim 1/1$	/_1		R No.	,
's	igned by	luts	Date	9/25/94 36 14100	
S	urveyor's Michigan License No1	4100		OFESSION FORM APPROVED BY MICHIGAN STATE BOARD TO SOME THEFTORS, JAN. 28.	
				RÉVISEÓ MAY 14. .MAC OBSIVAN	1975