SECTION.

Surveyors Michigan License No. 33967

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1971

For Corners in			
St. Joseph	Located In:	Comer Code #	LIBER 5 PAGE 229 STATE OF MICHIGAN
(County) 1. Public Land Survey	T_8SR_9W_	E-3	ST. JOSEPH COUNTY
	TR		FILED
	TR		22 DEC 1999 11:00:09 AH
	 		CYNTHIA L. JARRATT REGISTER OF DEEDS
2. Property Controlling	STR		MUDDICK OF DOLLAR
in Section	s TR	·	
3. Miscellaneous	srR		Register of Deeds Stamp & Filing Number
, -	S TR		
4. Lot No	, Recorded Plat		ABCDEFGHIJKL
5. Private Claims			2 6 5 4 3 2 1
P.A. 74, Michigan P.A. of 19; with regulations and rules the States Department of the International in that the corners mentioned in	70, the corner points mentioned erefor as required in the current erior, Bureau of Land Manager In lines 3, 4 and 5 above were in the by a Decree of a Court of Law	, do hereby certify that under require d in lines 1 and 2 above were in con nt manual of survey instructions of the ment or by a decree of a Court of La in conformance with the rules of the w; established, re-established, monu	rements of 4 7 8 9 10 11 12- informance 5 1 1 1 12- informance 5 1 1 1 13- informance 5 1 1 1 13- informance 5 1 1 1 13- informance 5 1 1 1 1 13- informance 5 1 1 1 1 13- informance 5 1 1 1 1 1 13- informance 5 1 1 1 1 1 1 13- informance 5 1 1 1 1 1 1 13- informance 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
NOTE: Not more than 2 Recorded on this	corners, all in the same to s certificate.	own and range, may be	10 30 29 28 27 26 25
A. Description of origina	I monument and accessorie	es and/or Subsequent restoration	n: 12 31 32 33 34 35 36
LCRC 4, PAGE 285			19
B. Description of corner	r evidence found and/or me	thod applied in restoring or reest	tablishing comer:
Found Remon Capped	Iron in Mon Box		
Geodetic Reference Sy having the PID of "AA8	ystem monument having 1117" with Station Name (han 0.08 feet relative to t	a position order of "B" incorpe of "IRS-F". The maximum pos	ications for Order "C 2-II". The closest the Nations orated in the traverse network was the monument sitional error of each Land Comer monument bein I monuments of the National Geodetic Reference
C: Description of monum	ent for corner and accessor	ries to perpetuate locating the po	osition of the corner:
Found Remon Capped	iron in Mon Box		
It's coordinates in inter	national feet are: Northir	ng 109533.3529, Easting 128	849854.5884
Witness: 10" Maple So	outh 49.75', UP N20°W 1	13.07', NW Cor. House 87.27	7', SW Cor. Building N82°E 54.54'
	,	ÓN AUG. I	CE WITH P.A. 345

REMONUMENTATION

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
REVISED OCT., 1996

33967 AROFESSIONAL