LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1971

		-
For Corners in		
St. Joseph	_ Located in: Corner Code #	
(County) 1. Public Land Survey	T 8S R 9W D-6	LIBER 5 PAGE 226
	TR	STATE OF MICHIGAN ST. JOSEPH COUNTY
	TR	FILED
	TR	22 DEC 1999 10:59:13 AM
2. Property Controlling	STR	CYNTHIA L. JARRATT
in Section	STR	REGISTER OF DEEDS
3. Miscellaneous	s	
Property in Sec.	Re STR	gister of Deeds Stamp & Filing Number
	, Recorded Plat	· ·
· · · · · · · · · · · · · · · · · · ·		A B C D E F G H I J K L M
5. Private Claims		2 6 + 5 + 4 + 3 + 2 + 1 - 3
i. Donald C. Andrews, in a	field survey on November, 1999, do hereby certify that under requirements	s of 4 7 8 + 9 + 10 + 11 + 12 -
P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefor as required in the current manual of survey instructions of the United		nce 5
States Department of the Ir	merior, Bureau of Land Management or by a decree of a Court of Law and in lines 3, 4 and 5 above were in conformance with the rules of the Michig	Vor 6 - 18 + 17 - 16 + 15 + 14 + 13 -
Board of Land Surveyors o	r by a Decree of a Court of Law; established, re-established, monument,	re- 8 -19 20 21 22 23 24
monumented, recovered, for	·	9
NOTE: Not more than Recorded on th	2 corners, all in the same town and range, may be als certificate.	10 -30 -29 -28 -27 -26 -25
A. Description of origin	al monument and accessories and/or Subsequent restoration:	12 -31 - 32 - 33 - 34 - 35 - 36
LCRC 4, PAGE 307		13
B. Description of corn	er evidence found and/or method applied in restoring or reestablish	ning corner:
Found Remon Cappe	d Iron in Mon Box	
Geodetic Reference S having the PID of "AA	y Land Comers being located were done within specification system monument having a position order of "B" incorporated 8117" with Station Name of "IRS-F". The maximum position than 0.08 feet relative to the connecting HARN control months confidence level.	d in the traverse network was the monument al error of each Land Comer monument being
C: Description of monur	ment for corner and accessories to perpetuate locating the position	of the corner:
Found Remon Cappe	d Iron in Mon Box	
It's coordinates in inte	mational feet are: Northing 101599.4669, Easting 1284711	7.7892
Witness: 32" Oak No	rth 25.88', 10" Hickory S85°E 29.6', UP S23°W 84.91', 16" C	Pak S78°W 133.83'
	RATIFIED BY PEER GR	ROUP OF MICHIG

IN ACCORDANCE WITH P.A. 345 QN, JUNE 10 , 1996 JUNE 10 , 1996 CO. REPRESENTATIVE 12/21/99 Wen

Surveyors Michigan License No. 33967

DONALD C. **ANDREWS** PROFESSIONAL SURVEYOR No. 33967 PROFESSIONAL

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
REVISED OCT., 1996
ADAPTED FOR WORD PROCESSING