

SURVEY & REMONUMENTATION
APR 10 1995
COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in St. Joseph
 (County)

Located In: _____ Corner Code ##

LIBER **4** PAGE **81**

STATE OF MICHIGAN
 ST. JOSEPH COUNTY
 FILED

20 DEC 94 12:36 P.M.

CYNTHIA JARRATT
 REGISTER OF DEEDS
 Register of Deeds Stamp & File Number

- 1. Public Land Survey T 8S R 10W C-1
- T _____ R _____
- T _____ R _____
- T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
- in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
- Property in Sec. S _____ T _____ R _____

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, Donald C. Andrews, in a field survey on November 30, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO - 1825 - Mullet - Set Post
 Co. Surv. NS Andrews Set stake & stones from bearing trees. Co. Rd. 1949 fd. stone and replaced with pipe/box, no wit.
 LCRC 2, P 283 Andrews 1/2" pipe/box, LCRC 3, P154 Mostrom pipe/box, LCRC 3, P 191 Mostrom 3/4" pipe/box, Surveys buy Mostrom 1976 pipe/box, 1986 3/4" pipe/box, NS Andrews 1877 field notes show set stone, 5 other Mostrom surveys used corner as monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

found 1/2"x36" pipe set in side monument box and distances check with witnesses as shown on LCRC 3, P. 191

RATIFIED BY PEER GROUP
 IN ACCORDANCE WITH P.A. 345
 ON Nov. 14, 1994
Allen CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Remon. capped iron in place of found pipe.

- 1) anchor post N45°W 41.10'
- 2) anchor post N42°E 43.75'
- 3) anchor post S40°W 47.59'
- 4) Vent pipe S44°E 50.30'



LIBER **4** PAGE **81**

Signed by Donald C. Andrews

Date 12-12-94

Surveyor's Michigan License No. 33967

REMONUMENTATION