## SURVEY & REMONUMENTATION

13 1996 O 3 1996

## LAND CORNER RECORDATION CERTIFICATE For corners in ST\_ Filing Requirement of Act 74, Mich. P.A. 1970 LIBER 4 PAGE 245 **JOSEPH** Located In: Corner Code # STATE OF MICHIGAN WHITE PIGEON TWP. ST. JOSEPH COUNTY T 85 R 11W 1. Public Land Survey G-2 FILED \_ R\_ 6 AUG 96 3:57 P.H. Т Τ\_ 2. Property Controlling R CYNTHIA JARRATT in Section S \_T \_ REGISTER OF DEEDS 3. Miscellaneous Т Register of Deeds Stamp & File Number Property in Section R \_ , Recorded Plat 5. Private Claims t, DAVID W. MOSTROM, in a field survey on MARCH 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (G-2) 1/4 CORNER COMMON TO SECTIONS 3 & 4, T 8 S, R 11 W 1867 SURVEY IN BOOK A, PAGE 150 8" MAPLE = N36°E 37.40' \* 1976 LCRC IN BOOK 3, PAGE 157 \* 1961 ROAD COMMISSION STAKE & STONE MIDWAY BETWEEN FOUND PIPE IN MON. BOX SECTION CORNERS LARGE STONE UNDER MON. BOX 18" MAPLE = N22°E 62.95" 3" MAPLE = N79-1/2°W 23.1" 25"MAPLE = N37°E 37.45" 18" MAPLE = N34°W 38.16" 4" MAPLE = N36°E 39.61 24" MAPLE = \$37°E 34.4" 18" B. WALNUT = \$40°E 34.30' IRON ANCHOR POST = \$86°W 35.0 1977 LCRC IN BOOK 2, PAGE 94 1969 CONSUMERS POWER SURVEY 1/2" PIPE IN MON. BOX 1.0'W. \* 1877 SURVEY IN BOOK A, PAGE 26 STONE SET FROM OLD BEARINGS 1969 CONSUMERS POWER SURVEY B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 8" MAPLE = N83-1/4°W 23.761 FACE OF GAS LINE MARKER = N20°E 109.12' FOUND 1/2" PIPE OVER POINTED STONE (18" DEEP) IN MON. BOX FACE OF GAS LINE MARKER = CL A ROAD = WEST 1.0' N20°W 77.47' CORNER FALLS IN PROJ. OF FENCE TO EAST 12" TWIN ELM = \$84°E 40.32" BROKEN OFFIRON ANCHOR POST = \$86°W 34.5'± P. POLE = S29°W 70.94' "T" IRON = EAST 33.03" FACE OF GAS LINE MARKER = N20°E 109.23' FACE OF GAS LINE MARKER = N20°W 77.51' RATIFIED BY PEER GROUP 12" TWIN ELM = \$84°E 40.32" IN ACCORDANCE WITH P.A. 345 ON March 11 . 1996 P. POLE = \$29°W 70.94' 1996 CO. REPRESENTATIVE C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: OF MICHIGA (G-2) 1/4 CORNER COMMON TO SECTIONS 3 & 4 T 8 S, R 11 W SET 5/8"X18" IRON BAR W/ STD. CAP OVER STONE IN MON. BOX CL OF GAS LINE MARKER = N20°E 109.341 **DAVID W** CL OF GAS LINE MARKER = N20°W MOSTROM 77.631 CONSUMERS POWER "T" IRON = EAST 33.03" PROFESSIONAL N & W 1.5' HIGH IN NW SIDE OF 14" MAPLE = S50°W 84.50' No. N&W 1.5' HIGH IN SE SIDE OF P. POLE = \$30°W 70.94' 32339

Date JULY 29, 1996

32339 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

N & W 1.5' HIGH IN N. SIDE OF 12" TWIN ELM = \$84°E 40.32'

Signed by

Surveyor's Michigan License No.\_

POFESSION