SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1971

For Comers in	TION		_	
St. Joseph	Located In:	Corner Code #	LIBER 5	PAGE 237
(County) 1. Public Land Survey	T 8 S R 12 W			STATE OF KICHIGAN ST. JOSEPH COUNTY
	TR			FILED
	TR	·		22 DEC 1999 11:02:36 AM
	TR			CYNTHIA L. JARRATT
2. Property Controlling	S T R			REGISTER OF DEEDS
in Section	STR			
3. Miscellaneous	SR			
Property in Sec.	S TR		Register of Deed	s Stamp & Filing Number
4. Lot No	_, Recorded Plat		A D	CDEFGHIJKLM
5. Private Claims				1
			3	J 4 3 2 1
I, _Donald C. Andrews, in a field survey onNovember, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in			oove were in 5	8 + 9 + 10 + 11 + 12
conformance with regulations and rules therefor as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of $-18 - 17 - 16 - 15 - 14 - 13$				
the Michigan Board of Land	d Surveyors or by a Decree of	5 above were in conformance wit of a Court of Law; established, n	e-established,	20 21 22 22 24
monument, re-monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be				
Recorded on th		town and range, may be	10 -30-	29 28 27 26 25
A. Description of original monument and accessories and/or Subsequent restoration:				32 33 34 35 36
LCRC 4, PAGE 250		•	13 📖	
	÷			
B. Description of come	er evidence found and/or m	ethod applied in restoring or re	establishing comer:	
Found Remon Capped Ir	on in Mon Box.			
Geodetic Reference S having the PID of "MD	ystem monument having 1335" with Station Name than 0.08 feet relative to	g a position order of "B" inco e of "Q 122". The maximum	orporated in the travers positional error of each	2-II". The closest the National se network was the monument th Land Corner monument being National Geodetic Reference
C: Description of monum	nent for corner and accesso	ories to perpetuate locating the	position of the corner:	
Found Remon Capped	I Iron in Mon Box	· · · · · · · · · · · · · · · · · · ·		
It's coordinates in inter	national feet are: Northi	ing 113027.2185, Easting	12748783.4104.	
Witness: UP N19°E 99	9.0', UP S12°E 169.19',	22" Maple N50°W 45.50', 6	" AP S17°E 108.18'	OF NO.
	.100	RATIFIED BY PEE IN ACCORDANCE I SEPT. 9 Ulun CO. REP 12/21/99	NITH P.A. 345	DONALD C. ANDREWS PROFESSIONAL SURVEYOR No. 33967

Surveyors Michigan License No. 33967

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995
ADAPTED FOR WORD PROCESSING

33967

PROFESSION

REMONUMENTATION