For Corners in

GECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1971

(County) 1. Public Land Survey	— —		LIBER	5 PAGE 238 STATE OF HICHIGAN ST. JOSEPH COUNTY FILED 22 DEC 1999 11:02:54 AM CYNTHIA L. JARRATT RESISTER OF DEEDS
in Section S 3. Miscellaneous S	TR TR TR			eds Stamp & Filing Number
I, Donald C. Andrews, in a field sur P.A. 74, Michigan P.A. of 1970, the with regulations and rules therefor States Department of the Interior, i that the corners mentioned in lines Board of Land Surveyors or by a t monumented, recovered, found as	rvey on November, 1995 e corner points mentione as required in the curre Bureau of Land Manage 3, 4 and 5 above were Decree of a Court of Land expressed below:	9, do hereby certify that under od in lines 1 and 2 above were not manual of survey instruction ment or by a decree of a Coul in conformance with the rules w; established, re-established,	requirements of 4 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 - 2 - 1 7 - 8 - 9 - 10 - 11 - 12 - 13 - 14 - 13 - 15 - 14 - 15 - 14 - 15 - 15 - 15 - 15
NOTE: Not more than 2 corn Recorded on this cert A. Description of original mon LCRC 4, PAGE 251	tificate.		ration: $ \begin{array}{ccc} 10 & -3 \\ 11 & -3 \\ 12 & -3 \\ 13 & -3 \end{array} $	0 29 28 27 26 25 1 32 33 34 35 36
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Remon Capped iron in Mon Box. The St. Joseph County Land Corners being located were done within specifications for Order "C 2-II". The closest the National Geodetic Reference System monument having a position order of "B" incorporated in the traverse network was the monument having the PID of "MD1335" with Station Name of "Q 122". The maximum positional error of each Land Corner monument being located would be less than 0.08 feet relative to the connecting HARN control monuments of the National Geodetic Reference System based on a 95% confidence level.				
C: Description of monument for Found Remon Capped iron i		ries to perpetuate locating ti	ne position of the corner	
It's coordinates in internation Witness: NE Cor. Garage S				Popular S42°W 45.65'
Signed by Lower License Surveyors Michigan License	<u>Undrewl</u> No. <u>33967</u>	RATIFIED BY PEER IN ACCORDANCE WON SEPT. 9 Mus Co. REPR 12/21/99 Wess.	ith p.a. 345 , 1996 Resentative	DONALD C. ANDREWS PROFESSIONAL SURVEYOR No. 33967 POFESSIONAL ARD OF LAND SURVEY SIN 28, 1871