

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Schoolcraft and  
Delta COUNTY


T 39 N R's 17 and 18W

DESCRIPTION OF CORNER Section corner for sections T39N 1/6 T39N  
R18W 12/7 R17W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/4/70, F. J. Bray

WITNESSES TO CORNER..... 7" Cedar (S.6) (NBT) N 21° E, 24.8'



8" Cedar (S.12) (NBT) S 51° W, 25.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from M. McNabb's NBT's. Found point of wood post. Cedar stumps to the NE and SW check with original notes as BT's. Corner lies in old winter logging road.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Frank J. Bray*  
REGISTERED LAND SURVEYOR  
Frank j. Bray

DATE

6/24/70

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68