

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40 N.R. 17 & 18


Schoolcraft & Delta COUNTY ^B

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner for 12/7

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 7-13-61

WITNESSES TO CORNER..... 6" Soft Maple ($\frac{1}{2}$ S NBT) N21°W 25 $\frac{1}{2}$ links



6" Soft Maple ($\frac{1}{4}$ S NBT) S07°E 05 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 2 B.T. stumps. Cedar 7, N85W, 6 links (face but no marks).

Hemlock 5, S17W, 5 links. (Notch and iron marks visible)

SURVEYOR'S SEAL

SIGNED Billy O. Buckler DATE January 31, 1962
REGISTERED LAND SURVEYOR
Billy ^U. Buckler