

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 13 W. . .

Schoolcraft

COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 4, 5, 8, 9

DESCRIPTION OF CORNER MONUMENT 2" pipe with 2 1/2" brass cap

WITNESSES TO CORNER	10" Cedar	Marked "S 4 NBT"	N 15° E	73 links
	8" Cedar	Marked "S 9 NBT"	S 43° E	25 links
	5" Cedar	Marked "S 8 NBT"	S 26° W	27 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed pipe as set by Carl Christianson, Manistique.

Found Spruce B.T., down in poor condition.

Shown to us by Carl Makel, D.F.

Corner re-witnessed January 9, 1957

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 1-11-57
REGISTERED LAND SURVEYOR