

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 NR. 13W

Schoolcraft

COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 5 - 8

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 1/4" brass cap

WITNESSES TO CORNER 9" Cedar N65°E 26 Links  
Marked "1/4S NBT"

5" Cedar N46°W 17 Links  
Marked "1/4S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed 1/4 Corner as set by Carl Christianson, Manistique.

One Tamarack B.T. in place in poor condition.

1/4 Corner lies in swamp. Placed location poster 4 chains north on trail road.

1/4 Corner shown to us by Jack Zollner, Ass't. Forester.

Corner placed and witnessed January 15, 1957.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

DATE

1-30-57