

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T.A.L. NR. 13.W.

Schoolcraft

COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 8, 9, 16, 17

DESCRIPTION OF CORNER MONUMENT 2 1/2" iron pipe with brass cap

WITNESSES TO CORNER	6" W. Pine	N 37° E	58 links
		" S 9 NBT"	
	6" W. Pine	N 18° W	112 1/2 links
		" S 8 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Section Corner as placed by Carl Christianson, Manistique, 1948.

One Y. Pine B.T. in place, bears S 4 1/2° W, 1.04 chains.  
Tree down and in excellent condition.

Corner shown to us by Jack Zollner, Ass't District Forester.

Corner is 2 1/2" pipe with brass cap.

Corner re-witnessed and placed 1-29-57.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2-7-57  
REGISTERED LAND SURVEYOR