

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Schoolcraft COUNTY  
T 41 N R 16 W

DESCRIPTION OF CORNER Meander corner on E-W 1/4 line of section 6

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/23/70, F. J. Bray

WITNESSES TO CORNER..... 8" Leaning cedar (NBT) S 20° E, 21.5'



5" Cedar (NBT) S 38° W, 14.9'

1/2" iron rod S 86° E, 8.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line between irons at 1/4 corner at lake shore.  
Both irons set by unknown party. Iron on lake shore may soon be lost due  
to water action.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

7/14/70

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68