FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Schoolcraft Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	1
I, PJBLIC LAND SURVEY	T. 41 8., R. 16 8.	D-8	
2. PROPERTY CONTROLL-20	.т. 41 ^N . R. 16 ^Ж .	. 8	
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. R E. W.		
4. LOT NO , RECOR	DED PLAT		
5, PRIVATE CLAIMS	··		REGISTER OF DEEDS

- 1. Description of original monument and accessories and/or subsequent restoration:
- -8 Center of Section 20. Not previest.

West 1/16 cor. of section 20 on the E-W 1/4 line. Not prev. est.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- -8 Set at the intersection of the N-S and E-W 1/4 lines of sec. 20 by closed traverse.

Set M.P.C.L. between the center of section and the W 1/4 cor. of section 20.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- -8 D.N.A. Monu. Bearings:

12" Cedar, N8°E, 29.1'
12" W. Birch, N84°E, 29.9'
7" Jedar, S26°E, 17.1
6" Jedar, S30 W, 25.2'

8 D.N.K. Monu. bearings:

4" Cedar, S52°W, 31.5 5" Cedar, S7°E, 25.1'

6" Ceder, N81°E, 25.9

SIGNED B. Ward B. Ballitt DATE 4-19-82

David E. Babbitt

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

STAMP AND