AND CORNER NECOMBATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Schoolcraft Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN -:	COL	RNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 41 N. R. 16	w. <u>C-7</u>	<b>,</b> D-7	_
2. PROPERTY CONTROLL- ING IN SECTION—	,TNN	E. W		_
3. MISCELLANEOUS PROPERTY IN SECTION —	, T N	E.	••.	_
4. LOT NO, RE	CORDED PLAT			_
5, PRIVATE CLAIMS			•	REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- C-7 Northwest section corner of section 20. Found 3" pipe with concrete as set by Gregory A. Shadko, L.S. in 1940.
- D-7 North 1/4 corner of section -20. Found 3" nipe with brass cap as set by Gregory A. Shadko, L.S. in 1940.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- C-7 Corner witnessed as set by Gregory A. Shadko, L.S. in 1940.
- D-7 Corner witnessed as set by Gregory A. Shadko, L.S. in 1940.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- C-7 3" pipe with concrete. New Bearings: 8" Tamarack, N23°W, 73.0' & R.O.W. Marker, N7°E, 40.2' & 7" Cedar, N47°E, 41.25' & P. Pole, N71°E, 35.1' & Center Line of Road, South, 18.2'.
- D-7 3" pipe with Erass Cap. New Eearings: 20" W. Pine, N80°W, 49.5' & 12" W. Pine N55°W, 19.5' & 8" W. Fine, N4°K, 34.7' & 10" W. Pine, S57°E, 37.0'.

SIGNED BY Lavid B. Balbitt	DATE 8-8-83		
David E. Babbitt	(SEAL)		