

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42-43 N.R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 5-6-31-32

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 5-23-61

WITNESSES TO CORNER..... 6" Jack Pine (S32 NBT) N70°E 14 links



7" Jack Pine (S5 NBT) S14°E 23 links

6" Jack Pine (S6 NBT) S55°W 35 links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Spruce Pine B.T., bearing N70°E 16 links. Stump cut low and in fair condition.
Corner lies in wet marsh.
Found while checking lines run by Forestry Division Survey Crew.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 28, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler