

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 42&43 N.R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 36 T43N R14W  
1/4 Corner between 1 T42N R14W

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5-9-61

WITNESSES TO CORNER..... 12" Soft Maple (1/4 S NBT) S63°W 36 1/2 links



9" Hard Maple (1/4 S NBT) N39°E 24 links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from wood post which seems to check well with corners in vicinity. No original evidence.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 28, 1961  
REGISTERED LAND SURVEYOR  
Billy D. Buckler